



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Ref: ~~CS3/GRB22007302/Tc~~
CS3/GRB22007302/Tce2-1
Date: ~~01/08/2022~~
25/08/2022
Code: GRB

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLQ 6114J	Veh. Inspected	FBQ 382J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	Bhuvaneswari	Assign Date	01/08/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	27/07/2022	Inspection Date	02/08/2022
Survey held at	GP SERVICE PTE LTD 282 MACPHERSON ROAD SINGAPORE 348607		

5a. Remarks

--	--