



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2205930

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 26/09/2022
Reference CS3/GRB22007302/Tce2-1
Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. FBQ 382J
Insured Veh. SLQ 6114J
Claim No. MFL2022D0004049
Policy No. D21MFL0000447_01
Accident Date 27/07/2022
Inspection Date 02/08/2022

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Less: Pre-Repair Survey Fee (Invoice.AC2205209 dated 23/08/2022)	-120.00
Subtotal	130.00
GST (7%)	9.10
Grand Total	139.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM