

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Immediate Advice

To: HSBC Life (Singapore) Pte. Ltd. Date: 14/06/2023

Survey Details:

Date of loss	20-Sep-2022	
Date of appointment	22-Sep-2022	
Date of survey	22-Sep-2022	
Location of survey	MG SOLUTION PTE LTD	

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM	
Vehicle number	GBA1672A	
Make and Model	TOYOTA HIACE MANUAL	
Date of registration	27-Mar-07	
Market Value	\$	40,000.00
Parf Rebate	\$	19,900.00
Nett Loss	\$	20,100.00

Repair details:

Initial Estimate	10,502.80
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 3,680.25
Check items (estimate)	\$ -
Labour	\$ 2,150.00
Total	\$ 5,830.25
Lump Sum(if applicable)	\$ 4,600.00

Number of days for repair	6.0



 $51\,UBI\,AVE\,1, \#02-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,TEL: (065)\,62563561\,FAX: (065)\,62564315$

Remarks:

OID TURNED OUT FROM MINOR ROAD TO MAJOR AND COLLIDED
WITH TP WHO WAS TURNING FROM MAJORROAD TO MINOR
ROAD.

Mandate:

Liability(TP)	80%	
Proposed repair cost	\$ 4,968.00	(WITH GST)
Loss of use	\$ 800.00	(8DAYS X \$100.00)
Loss of rental	NIL	no. of days
Loss of income	NIL	no. of days
LTA search fees	\$ 7.45	
Others	NIL	
Proposed Total	\$ 5,775.45	