

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Sep 2022)

Parts: N/A MITSUBISHI CANTER 3.0 D FEB71ER4SDEC (CBU) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/YQ3990L/22/09/2022 18:38

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

H. Kenneth

YQ3990L

OD/Al/1ak2

Carter

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC FRT BUMPER	R ₁ 0.00	0.00	*490.00 F ✓
2	1		*1 PC FRT BUMPER LH SIDE PAD	MT 0.00	0.00	*180.00 F ✓
3	1		*1 PC FRT BUMPER LH BRACKET	R ₁ 0.00	0.00	*98.00 F ✓
4	1		*1 PC FRT BUMPER LH STAY	R ₁ 0.00	0.00	*85.00 F ✓
5	1		*1 PC FRT BUMPER RH BRACKET	R ₁ 0.00	0.00	*98.00 F ✓
6	1		*1 PC FRT GRILLE	CM 0.00	0.00	*550.00 F ✓
7	1		*1 SET FRT GRILLE CLIP	RU 0.00	0.00	*24.00 F ✓
8	1		*1 PC LH SIGNAL LAMP	R ₁ 0.00	0.00	*150.00 F ✓
9	1		*1 PC LH HEADLAMP	SM 0.00	0.00	*280.00 F ? X
10	1		*1 PC FRT LH CORNAL GARNISH	CM 0.00	0.00	*120.00 F ✓ 270 ✓
11	1		*1 PC FRT PANEL	R ₁ 0.00	0.00	*520.00 F ✓
12	1		*1 PC FRT WIPER GARNISH	WAP 0.00	0.00	*195.00 F ✓
13	1		*1 PC FRT WINDSCREEN RUBBER	WT 0.00	0.00	*200.00 F ✓
14	1		*1 PC FRT LH SIDE MIRROR ROUND	MT 0.00	0.00	*45.00 F ✓
15	1		*1 PC FRT LH SIDE MIRROR SQUARE BACK COVER	MT 0.00	0.00	*28.00 F ✓
16	1		*1 PC AIRCON EVAPORATOR	(100) CM 0.00	0.00	*1,650.00 F ✓ 1600 ✓
17	1		*1 PC CABIN FRT LH MOUNTING	DT 0.00	0.00	*395.00 F ✓
18	1		*1 PC CABIN FRT MOUNTIN CROSS BAR	R ₁ 0.00	0.00	*380.00 F ✓
19	1		*1 SET AIRCON HEATER PIPE	0.00	0.00	*160.00 F ✓
20	1		*1 PC HORN	OD 0.00	0.00	*55.00 F ✓ 85 ✓
21	1		*1 PC AIRCON GAS DISCHARGE HOSE	SM 0.00	0.00	*150.00 F ✓
22	1		*1 PC AIRCON GAS RECEIVER HOSE	SM 0.00	0.00	*165.00 F ✓
23	1		*1 PC BRAKE OIL PIPE	SM 0.00	0.00	*170.00 F ✓

F=Franchise part.

Sub Total (\$\$)

6,188.00

+ Margin on L,N Items 10.00% (\$\$)

618.80

Total Parts (\$\$)

6,806.80

Cheng Hoe Motor Pte Ltd/YQ3990L/22/09/2022 18:38. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 PC FRT NO. PLATE	
2	1	1 PC FRT NO. PLATE	R ₁ 20.00 ✓
Sub Total (\$\$)			20.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
----	-------------	----------	--------

Cheng Hoe Motor Pte Ltd/YQ3990L/22/09/2022 18:38. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Labour Items

1	1) TO REMOVE AND REFIX FRT WINDSCREEN GLASS	New	100.00	✓
2	2) TO REMOVE AND REFIX AIRCON, CHECK, VACUUM AND REFILL GAS	New	100.00	✓
3	3) TO REMOVE AND REFIX DASH BAORD, METER ASSY AND CHECK WIRING	New	280.00	250
4	4) TO PANEL BEATING INCLUDE STRAIGHTEN FRT LH WS PILLAR AND RE-ALIGN CABIN POSITION	New	800 1,000.00	
5	5) TO PUTTY AND RESPRAY ON FRT PANEL, FRT CORNAL PANEL, FRT GRILLE, BUMPER, BRACKET, FRT LH WS PILLAR	New	700 800.00	

Gross Labour Cost (S\$)

2,280.00

Cheng Hoe Motor Pte Ltd/YQ3990L/22/09/2022 18:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts \$ 5393
 Supp \$ 403
 Add 10% 579.60
 20 SN
 1950
 \$ 8345.60

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Sep 2022)
 Parts: N/A MITSUBISHI CANTER 3.0 D FEB71ER4SDEC (CBU) (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: **Cheng Hoe Motor Pte Ltd/YQ3990L/30/09/2022 09:37**
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC LH HEADLAMP LOWER RUBBER	0.00	0.00	8.00 F ✓
2	1		*1 PC AIRCON GAS PIPING NO. 3	0.00	0.00	260.00 F ✓
3	1		*1 PC CABIN FRT LH MOUNTING CUSHION	0.00	0.00	120.00 F ✓
4	1		*1 PC CABIN RH HINGE BUSHING	0.00	0.00	15.00 F ✓
Sub Total (S\$)						403.00
+ Margin on L,N Items 10.00% (S\$)						40.30
Total Parts (S\$)						443.30

F=Franchise part.

Cheng Hoe Motor Pte Ltd/YQ3990L/30/09/2022 09:37. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Cheng Hoe Motor Pte Ltd/YQ3990L/30/09/2022 09:37. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

8345.60