

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

Roc: 53360061L

GST: 53360061L

Stem (LKK)
20/9/21, 19.30a
wil R
p/p
by BL sy
3 d/s

QT21/CB7359Z/TPC

AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way
#07-16
Singapore 079120

QUOTATION

Dear Sir,

Cost of Repair to Vehicle CB7359Z

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front bumper / CUT -15%	1	733.80	733.80
2.	Front bumper clips - 11/c S/N	10	3.00	30.00
3.	Front LH side lamp - BR -15%	1	148.20	148.20
4.	Check wiring	1	30.00	30.00
5.	Labour charges	1	600.00	600.00
6.	Spray painting	1	300.00	300.00
SUB-TOTAL				S\$1,842.00

- Price before 7% GST

CAL SLIP -

733.8

148.2

882.00

-15%

749.7

+30sn

779.70

labour 30

250

300

p/p 1,359.70

Thank you.

Yours faithfully,

 

Winnie Chai
HP: 9850-9666

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: