



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22009403/Kny3q2 Date: 07/10/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKE 1528G	Veh. Inspected	SHD 5831U	
Policy No.	P10780535R00	Coverage (\$)	0.00	
Claim No.	C10017662/JY	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	23/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTDKB3FU603075072	Colour	M.P.WHITE/RED	
Odometer	378076 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FIRENZA	8 mm	
L/H Front Tyre	195/65 R15	SAILUN	9 mm	
R/H Rear Tyre	195/65 R15	SAILUN	9 mm	
L/H Rear Tyre	195/65 R15	SAILUN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/09/2022	Inspection Date	23/09/2022	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2.500 Working Days		