

CTZ / 220071111

Not Authorized
11 Sep @ 5700h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5831U

AAD2209-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD5831U

JTDKB3FU603075072

200303878K

TOYOTA

PRIUS

22/09/2022

SKE1528G/AUTO GEN

01/11/2018

PART

- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 LAMP ASSY, FOG, LH
- 1 UNIT ASSY, HEADLAMP, LH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 EMBLEM, SIDE PANEL LH
- 1 LINER, FRONT FENDER, LH
- 1 RIM
- 1 RIM

LIST

\$	516.00	✓
\$	79.60	X
\$	716.60	X
\$	346.00	X
\$	170.10	X
\$	47.50	X
\$	59.30	✓
\$	951.40	X
\$	2,637.60	✓
\$	977.80	✓
\$	54.60	✓
\$	202.50	X
\$	1,900.10	✓
\$	1,900.10	✓

TOTAL \$ 10,559.20

25% \$ 2,639.80

\$ 7,919.40

Special Nett

- 1 FRT BUMPER CLIP
- 1 TYRE
- 1 FENDER CLIP
- 1 FENDER LINER CLIP
- 1 FRT LH BUMPER RETAINER CLIP

TOTAL

\$	65.00	65.00
\$	180.00	180.00
\$	130.00	X
\$	130.00	X
\$	65.00	X
\$	740.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5831U

AAD2209-

TOTAL PARTS \$ 8,659.40**LABOUR**

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Panel Beating, Knocking And Straightening The Necessary

Portion, Remove And Renewal Of Parts, Adjust And Realign

The Same

\$ 1,400.00 400/

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 440/

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 30/

To Check Electrical Lighting Concerned.

\$ 170.00 15/

TOTAL \$ 3,590.00**Over All Total \$ 12,249.40****(PART-BY-PART) Repair Days**

20 days

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: