

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 8811U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE	BUCKLED	1,852.50	1,852.50
1	REAR TAILGATE DOOR LOCK	CUT	190.00	190.00
1	STICKER DOOR LATCH & STABILIZER SWING GATE	NOT NECESSARY	196.00	-
2	REAR TAILGATE HINGES TOP & LOWER @\$270.00	NOT NECESSARY	540.00	-
2	REAR TAILGATE HINGES COVERS TOP & LOWER @ \$180.00	NOT NECESSARY	360.00	-
1	REAR TAILGATE STRAP RETAINING	NOT NECESSARY	293.00	-
1	REAR TAILGATE DOOR HANDLE	NOT NECESSARY	208.30	-
1	REAR TAILGATE EXHAUSTER	DEFORMED	140.00	140.00
1	REAR TAILGATE TRIM PANEL	DEFORMED	120.00	120.00
1	REAR BUMPER	DEFORMED	2,936.40	2,936.40
2	REAR NUMBER PLATE LAMP @\$90.60	DISTORTED	181.20	181.20
1	REAR NUMBER PLATE	DISTORTED	50.00	50.00
1	REAR NUMBER PLATE SUPPORT	DISTORTED	170.00	170.00
1	REAR REVERSE CAMERA	DISTORTED	280.00	280.00
1	REAR CANOPY COVER	NOT NECESSARY	846.00	-
	LESS 10% DISCOUNT		-	-592.01
			8,363.40	5,328.09
	<u>LABOUR</u>			
	PANEL BEATING.		900.00	400.00
	CHECK WIRING.	NOT NECESSARY	120.00	-
	TO REMOVE AND REPLACE REVERSE CAMERA.		80.00	40.00
	TO SPRAY PAINTING.		620.00	200.00
			1,720.00	640.00
	GRAND TOTAL		10,083.40	5,968.09



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	4,200.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI22009405/Gqy3e2

MARKET VALUE: \$179,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$79,402.00=NETT VALUE: \$99,598.00

XING GUO QIANG

M.MATAI, AMSAE-A
Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.