

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jacqueline Tan

Date: 25 Jul 2023

**Preliminary Advice**

|                    |                                                                                                           |                         |              |
|--------------------|-----------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SMJ1955G                                                                                                | Accident Date           | : 20/09/2022 |
| TP Vehicle No      | : SJH8666R                                                                                                | Assignment Date         | : 02/10/2022 |
| Make               | : OPEL ASTRA ST                                                                                           | Est. Duration of Repair | : 4          |
| Date of Inspection | : 26/09/2022                                                                                              |                         |              |
| Inspection At      | : H S AUTOMOTIVES PTE LTD (HQ)<br>BLK 2 KAKI BUKIT AVENUE 2 #01-15 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |          |              |
|-----------------------------|----------|--------------|
| Repairer's Estimate (Gross) | :S\$     | 17,313.00    |
| Revised Amount              | :S\$     | 6,189.20     |
| Check Items (Estimated)     | :S\$     | 0.00         |
| Total                       | :S\$     | 6,189.20     |
| <br>Lump Sum Repair         | <br>:S\$ | <br>4,900.00 |

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.