

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 29 Sep 2022

Preliminary Advice

Vehicle No	: SJB8560T	Accident Date	: 20/09/2022
Make	: TOYOTA CAMRY	Policy No.	: MPC21P00213200
Assignment Date	: 23/09/2022	Excess	: S\$0.00
Date of Inspection	: 23/9/2022	Est. Duration of Repair	: 10
Inspection At	: CONVERGENCE AUTOMOTIVE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,203.00
Revised Amount	:S\$	8,291.50
Check Items (Estimated)	:S\$	3,795.00
Total	:S\$	12,086.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	147,000.00
COE / PARF Rebate	:S\$	50,777.00
Salvage Value	:S\$	
Margin for Repair	:S\$	96,223.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending investigation

Part by part repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .