

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AUTOMOTIVE ENG	GRG. & MGT. DIVISION (TP)	Ref:		
	FORCE) POLICE L	S SECTION (SPORE POLICE OGISTICS BASE (PLB) 1 SINGAPORE 438675	Date	e: 18/01/2023	
	ATTN: HAFIZUL FA	ARHAN	Cod	le: SPF	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.		Veh. Inspected	SKA 1219U	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	T/20220921/7043	Excess (\$)	0.00	
	Assign From	HAFIZUL FARHAN	Assign Date	23/09/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS C 1.5 HYBRID	c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour	BLACK	
	Odometer	124182 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/60 R15	MICHELIN	6 mm	
	L/H Front Tyre	185/60 R15	MICHELIN	6 mm	
	R/H Rear Tyre	185/60 R15	MICHELIN	6 mm	
	L/H Rear Tyre	185/60 R15	MICHELIN	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5.	General Information				
	Accident Date	21/09/2022	Inspect Date / Time	23/09/2022 ( 03:30 PM )	
	Survey held at	•			
	Repairer	•			
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$17,000-\$19,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days				

Report Ref No. CS3/SPF22009414/Gvy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.