



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22009428/Eqy3	
			Date: 26/09/2022	
			Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBL 1127A	Veh. Inspected	SBS 3816U
	Policy No.		Coverage (\$)	0.00
	Claim No.	2022 22006898KC	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	26/09/2022
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	16/09/2022	Inspection Date	26/09/2022
	Survey held at	Ulu Pandan WS, 1 Business Park Drive, Singapore 6		
	Repairer	SBS TRANSIT LTD (HQ)		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			