



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0062272 / UNITED
Chassis No: MRHFC5650JT000986
License No: SMC4659D
Mileage: 45694
Engine No: R16B25501090

Document No: SVO22043117
Printed By: IVANTEO
Order Date: 27. September 2022
Order Time: 2:17:25 PM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LIM SIU BOON OWNER INSURER: SINGLIFE ACC DATE: 22/09/2022 SURVEYED BY: DATE: REF NO: TP INSURER: UOI TP VEH: YQ1216C SUPPLEMENTARY PART						
68500-TEA-N00ZZ	LID COMP TRUNK	1	724.70	25	543.52	38.05	581.57
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	116.10	25	87.07	6.09	93.16
75722-TBA-A00	EMBLEM SETRR.	1	13.60	25	10.20	0.71	10.91
75725-TEA-T01	EMBLEMRR.	1	12.70	25	9.52	0.67	10.19
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	42.00	25	31.50	2.21	33.71
71503-TEA-T00	GARNISH,R.RR.BUMPER SIDE	1	9.00	25	6.75	0.47	7.22
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	190.10	25	142.57	9.98	152.55
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
66100-TEC-307ZZ	PANEL SETRR.	1	280.70	25	210.52	14.74	225.26
33500-TEA-T01	TAILLIGHT ASSYR.	1	301.70	25	226.27	15.84	242.11
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	30.80	25	23.10	1.62	24.72
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
	SUM PARTS:				1,863.49	130.45	1,993.94
BOSUN		1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I		1	250.00		250.00	17.50	267.50
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BA02R		1	250.00		250.00	17.50	267.50
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BMI03D		1	325.00		325.00	22.75	347.75
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BKTRR		1	325.00		325.00	22.75	347.75
	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID ADJUST & ALIGN.						
BC012R		1	500.00		500.00	35.00	535.00
	RESET VEHICLE SMART ENTRY SYSTEM						
BC011R		1	500.00		500.00	35.00	535.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA						
BKRP02S		1	2,600.00		2,600.00	182.00	2,782.00
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	CU0062272 / UNITED	Document No:	SVO22043117			
Chassis No:	MRHFC5650JT000986	Printed By:	IVANTEO			
License No:	SMC4659D	Order Date:	27. September 2022			
Mileage:	45694	Order Time:	2:17:25 PM			
Engine No:	R16B25501090	Service Advisor:	IVAN TEO BOON KIAT			
BP05R	1847	1	2,600.00	2,600.00	182.00	2,782.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)					
		SUM LABOUR:	7,370.00	515.90	7,885.90	
		TOTAL SGD	9,233.49	646.35	9,879.84	
		Total Payable (SGD)			9,879.84	

GST Amount is calculated from individual line(s)