

FASTECH AUTO PTE LTD  
 1 Kaki Bukit Ave 6 #01-48 Autobay  
 Singapore 417883  
 Tel No: 67452063/ 67467158 Fax No: 67458520  
 Tax Reg No : 200006262D

25/10/2022

Not Authorized  
 dlr  
 26/09/22  
 2/5 \$ 6200 /  
 4 days

VEHICLE No: SMM 6193P

QTY	DESCRIPTION	REMARKS	UNIT PRICE	TOTAL PRICE
1PC	FRONT BUMPER	Dis/Yoin	980	\$1,121.90 /
1PC	FRONT BUMPER SIDE RETAINER O/S	one		\$65.50 /
1SET	FRONT BUMPER CLIPS	all		\$39.00 /
1PC	FRONT BUMPER REINFORCEMENT	11		\$387.80 X
1PC	FRONT BUMPER FOG LAMP O/S	one	485.00	\$566.50 /
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	1w	380.00	\$381.90 /
1PC	HEADLAMP ASSY O/S	one	1525.00	\$1,815.20 /
1PC	FRONT FENDER O/S	bul	925	\$1,155.20 /
1PC	FRONT FENDER INNER SHIELD O/S	7orn	248	\$266.20 /
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	all		\$39.00 /
1PC	FRONT FENDER INNER ARCH PANEL O/S	R		\$691.30 X
1PC	BONNET	7D/bul	2170	\$2,291.00 /
1PC	FRONT SUPPORT PANEL	one	900	\$1,015.00 /
1PC	FRONT GRILLE	See		\$680.00 X
1PC	FRONT SPORT RIM O/S	R		\$800.00 X
				\$10,515.50

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$80.00	60
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	\$120.00	50
TO CONDUCT WHEEL ALIGNMENT	\$120.00	60
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,000.00	700
TO PUTTY & SPRAY PAINTING	\$1,200.00	700
<b>TOTAL</b>	<b>\$13,085.50</b>	

2-7257.50  
 202  
 6205.2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: