

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

*AXIT*

Name : **Ali Akbar Bin Shaibani**  
(81336372)

Accident Date : **14-Sep-22**

*not added  
new  
mercy  
27/9/22*

Vehicle No : **FBN6714L (COE211128)**

Vehicle Model : **Honda Supra  
GTR 150 Manual**

## Estimated Repair Costs

*45 \$900*

Qty	Description <u>List Items</u>		Amount S(\$)
		<i>r/s 3 days</i>	
1	Handle bar		168.00 ✓
1	Handle bar end	<i>30</i>	106.00 ✓
1	Hand grip (1 set)		68.00 X
1	Side mirror - R/H		120.00 X
1	Fairing assy (1 set)		680.00 X
1	Front footrest bracket - R/H		185.00 X
1	Front footrest - R/H	<i>75</i>	95.00 ✓
1	Brake pedal		105.00 X
1	Rear footrest - R/H		90.00 X
1	Rear footrest bracket - R/H		160.00 X
1	Exhaust assy		685.00 X
1	Exhaust protector		108.00 ✓
1	Exhaust protector end cover	<i>60</i>	88.00 ✓
1	Rear number plate lamp		105.00 X
1	Rear taillamp		220.00 X
1	Rear fender		165.00 ✓
1	Rear number lamp top cover		130.00 ✓
1	Rear wheel rim		480.00 X
1	Rear rim shaft		105.00 X
1	Rear rim bearing		80.00 X
1	Rear brake disc		185.00 X
1	Swing arm		620.00 X
			<b>4,748.00</b>
		Less 10%	474.80
			<b>4,273.20</b>

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : **Ali Akbar Bin Shaibani**  
(81336372)

Accident Date : **14-Sep-22**

Vehicle No : **FBN6714L (COE211128)**

Vehicle Model : **Honda Supra  
GTR 150 Manual**

## Estimated Repair Costs

### Special Net Items

1	Number plate (1 set)	<i>Rear Bent</i>	\$	38.00	<i>/2</i>
1	Sticker	<i>11</i>	\$	125.00	<i>X</i>
1	Rear box	<i>cut</i>	\$	480.00	<i>250</i>
1	Rear box bracket	<i>11</i>	\$	180.00	<i>X</i>
1	Rear tyre	<i>11</i>	\$	230.00	<i>X</i>
			\$	<u>1,053.00</u>	


### S/No.    Labour

1	To provide towing service (LOD)		\$	-	
2	To check wiring and reset headlamp focusing	<i>11</i>	\$	80.00	<i>X</i>
3	To provide rear body repair	<i>11</i>	\$	420.00	<i>X</i>
4	To provide labour		\$	480.00	<i>250</i>
			\$	<u>980.00</u>	

**Grand Total**

**\$ 6,306.20**

Singapore Dollars: Six Thousand Three Hundred Six and Cents: Twenty only

  
EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*p- 736*  
*102*  
*662-4*  
*512*  
*1174.4*