

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMN7080U/2209126

26th September 2022

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

*Not Bullard
Ler
P/P 8 1288
3 days.
15/11/22
Wah phb Aka ny-*

Date of Accident : 25th September 2022
Location : Upper Bukit Timah Road
Third Party Claim Vehicle No : SKH 1947 P
Repair Cost For Vehicle No : SMN 7080 U Honda Freed

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear door LH <i>n</i>	1	1,105.40	\$ 1,105.40 <i>x</i>
2	Rear door sticker LH <i>11</i>	1	42.50	\$ 42.50 <i>x</i>
3	Rear door w/strip LH <i>11</i>	1	425.40	\$ 425.40 <i>x</i>
4	Rear fender LH <i>n</i>	1	1,010.90	\$ 1,010.90 <i>x</i>
5	Rear wheel hub cab LH <i>cu7</i>	1	321.40	\$ 321.40 <i>/</i>
6	Rear door outer frame moulding LH <i>11</i>	1	76.40	\$ 76.40 <i>x</i>
7	Rear door quarter glass moulding LH <i>11</i>	1	149.20	\$ 149.20 <i>x</i>
				\$ 3,131.20
Less			20%	\$ 626.24
				\$ 2,504.96

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMN7080U/2209126

26th September 2022

Balance b/f \$ 2,504.96

Labour Charges :-

	<u>Amounts</u>	
Cut out, renew, knocking & welding, rear door assy LH, rear fender LH, running board panel LH, renew & install all damage parts & re-align body	\$ 800.00	550
Remove & install rear door board, door glass and lock & etc	17 \$ 120.00	X
Spray painting on damage parts	\$ 900.00	450
Tuff-kote on damage parts	17 \$ 120.00	X
Remove & install rear quarter glass	17 \$ 60.00	X
Check door wiring after repairs	17 \$ 30.00	X
Computerise wheel alignment	\$ 180.00	60
Labour Charge	\$ 2,210.00	1060
Total Amount	\$ 4,714.96	

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-285
207
228
1060
1288