

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN	ICE LTD	Ref:	CS/INC22009484/Any3e2	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557	Date	: 20/12/2022	
	ATTN: AZHARI AF	IDI	Code	e: INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMR 2054H	Veh. Inspected	SNA 8061A	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1186347-002	Excess (\$)	0.00	
	Assign From	ANNIE KOH	Assign Date	27/09/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALTIS	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2021	
	Chassis No.	MR2BE3BE300015296	Colour	WHITE	
	Odometer	73640 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	MICHELIN	6 mm	
	L/H Front Tyre	225/45 R17	MICHELIN	6 mm	
	R/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
	L/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
				1	
5.	General Information				
	Accident Date	26/08/2022	Inspect Date / Time	27/09/2022 (12:42 PM)	
	Survey held at	MG SOLUTION PTE LTD	<u> </u>		
	23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				
	1				