

AB ENGINEERING PTE LTD

Co. Reg No: 202117273R

10 KAKI BUKIT ROAD 2 #01-25, FIRST EAST CENTRE, SINGAPORE 417868

Tel : 8858 6282

SUPPLEMENTARY COST ESTIMATE

Vehicle No: SMZ9699J

Report No : SA1X229Q0001

Chassis No: JTJBZMCA802011436

Engine No: SNB2574X

Date : 29/9/2022

MAKE: TOYOTA

MODEL: LEXUS RX350 LUXURY AT SR

TYPE : Private Car

Replacement of Damaged Parts

S/No.	Description	Qty	Our Recommendation
Parts Items			
1	Air guide - LH CRA	1	\$123.80 45
2	Cornering Lamp - LH BR	1	\$1,174.20 435
3	Front sensor - LH CUT	1	\$480.90 280
4	Headlamp Nozzle - LH BR	1	\$914.90 274
5	Fog Lamp Bracket - LH BR	1	\$169.90 55
6	Front bumper sponge CRA	1	\$118.90 ✓
			\$2,982.60 1207.9
Less 10%			\$298.26
Total Parts:			\$2,684.34 1087.11
Add GST 7%			\$ 187.90
Total			\$ 2,872.24

Geo AG
29/9

parts - 10,1315.90 → 9,284.31
Supplementary. → 2,684.34
Labour + 80 (Additional) 1210

Additional part

13,178.65
80.00

13,258.65