

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 11 November 2022 9:19 AM
To: geraldph@lonpac.com
Cc: MT_Claim_SG; Admin A
Subject: RE: RE: GBJ3007K & YN1141A DOA.23.09.2022
Attachments: EMAIL FROM LPC DD 131022.pdf; LKK SURVEY REPORT & PHOTOS.pdf; GBJ3007KLOD.pdf

Your ref: **22/22/22/VC05/026327**
Our ref : CC4/LPC22009513/Kpa3q2

Dear Sirs/Mdm,

ACCIDENT INVOLVING YN1141A(LONPAC) AND GBJ3007K(TP) ON 23/09/2022

We refer to the above matter.

Based on third party video footage, we are of the view that liability is not in our driver's favour as he has encroached into third party's lane and collided with third party. Insured driver should exercise caution before make a lane change.

We seek your approval to offer repairer **"THINK ONE AUTOCARE PTE LTD"** at **\$1,766.00(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 8,222.31	\$ 1,284.00 (\$1,200.00 + 7%GST)
2. Loss of USE (4days x \$120.00)	\$ 480.00	\$ 480.00 (4DAYS X \$120.00)
3. INSURANCE SEARCH FEE	\$ 7.45	\$ 2.00
Total	\$ 8,709.76	\$ 1,766.00

Surveyor recommended 4days for repair.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 08/11/2022 is only for mandate purpose.

Kindly let us have your approval / instruction.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com |

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Tuesday, 4 October 2022 8:21 AM

To: geraldpoh@lonpac.com

Cc: MT_Claim_SG <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: RE: GBJ3007K & YN1141A DOA.23.09.2022

Dear Sirs/Mdm,

Enclosed for your perusal is: -

- Estimated cost of repair.
- Preliminary advice.
- Photographs of TP vehicle in its damaged condition.
- 3rd party video footage

Based on third party video footage, we are of the view that liability is not in our driver's favour as he has encroached into third party's lane and collided with third party. Insured driver should exercise caution before make a lane change.

Please let us have comments/instruction if we may proceed DS.

Thank you.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com |

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Tuesday, 27 September 2022 10:05 AM

To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; Admin A <admin-a@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>
Subject: RE: RE: GBJ3007K & YN1141A DOA.23.09.2022

Dear Gerald,

Thank you for the assignment.

Please be informed that vehicle not in the workshop, repairer will arrange.

Best Regards,

Yan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent: Tuesday, 27 September 2022 9:28 AM

To: 'assignments' <assignments@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: FW: RE: GBJ3007K & YN1141A DOA.23.09.2022

Lonpac External - General

Our Ref : 22/22/22/VC05/026327

Dear Yan,

FYNA. Attached copy of insured report.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/06 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

We are committed to acting professionally, fairly and with integrity. We do not condone bribery, fraud or corrupt practices.

From: Michael <michaelng@thinkone.com.sg>

Sent: Tuesday, 27 September 2022 9:06 am

To: MT_Claim_SG <mt_claim@lonpac.com>

Subject: FW: RE: GBJ3007K & YN1141A DOA.23.09.2022

Dear Sir / Mdm.

We would like to arrange for survey GBJ3007K vehicle stall at Think One Autocare Pte Ltd
No: 60 Jalan Lam Huat #02-32 Carros Centre postal code 737869

Thank you & Regards
Michael Ng
91288488