



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA			Ref: CC4/ASM22009516/Upa3q2 Date: 08/11/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMK 701Z	Veh. Inspected	SKZ 873E
	Policy No.	GA548219	Coverage (\$)	0.00
	Claim No.	S2M04BQS	Excess (\$)	0.00
	Assign From		Assign Date	27/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 320i (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	WBAPG560X0NM18855	Colour	BLACK
	Odometer	262881 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/35Z R19	NEXEN	6 mm
	L/H Front Tyre	235/35Z R19	NEXEN	6 mm
	R/H Rear Tyre	265/30Z R19	NEXEN	6 mm
	L/H Rear Tyre	265/30Z R19	NEXEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/09/2022	Inspection Date	27/09/2022
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	