

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	302A
Vehicle Details	
Vehicle No.:	GBL9475S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Sep 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	SPRINTER 316CDI 3665 4X4 VAN
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	65195533604436
Chassis No.:	WDB9066332P302059
Maximum Power Output:	-
Open Market Value:	\$62,064.00
Original Registration Date:	12 Oct 2017
First Registration Date:	12 Oct 2017
Transfer Count:	1
Actual ARF Paid:	\$3,104.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Oct 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$21,792.00
Total Rebate Amount:	\$21,792.00

The information contained herein is correct as at 27 Sep 2022

OK

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Legacy Logistic Services
Blk 26 Marsiling Dr
#03-221
Singapore 730026

Vehicle No : GBL 9475 S
Make/Model : Mer Van - Sprinter 316 Cdi 3665 4X4
Year : 2017

*Not Authorized
11/11 @ 9850/h
Return After Paint
8 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front bonnet	1218	473.75	PA	\$1,550.00	✓
1 pc	Front o/s fender			PA	\$750.00	✓
1 pc	Front o/s fender inner panel			PA	\$1,650.00	✓
1 pc	Front o/s fender innershield			Di	\$205.00	✓
1 pc	Front o/s fender lamp			su	\$195.00	X
1 pc	Front o/s headlamp	830		BRU	\$855.00	✓
1 pc	Front grille			PA	\$625.00	X
1 pc	Front grille frame			su	\$355.00	X
1 pc	Front support panel			CMA	\$675.00	✓
1 pc	Front o/s support garnish	photo		Di	\$105.00	✓
1 pc	Front bumper	1090		PA	\$1,275.00	✓
1 pc	Front bumper reinforcement	658		PA	\$850.00	✓
1 pc	Front o/s bumper side retainer			Di	\$175.00	✓
1 pc	Front o/s fog lamp			Di	\$385.00	✓
1 pc	ABS pump	photo	3210	CMA	\$3,850.00	✓
					\$13,500.00	
					Less 10 %	\$1,350.00
						\$12,150.00

Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting etc.	\$1,400.00	900l
To putty and spray paint - 4 portions	\$1,200.00	750l
Check & reconnect wiring.	\$45.00	20l
To respray anti-rust proofing treatment	\$120.00	90l
Remove/refit air con condenser & to top up gas.	\$180.00	100l
Remove/renew ABS pump and to reset same.	\$280.00	150l
Total	\$15,375.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before ~~after~~ spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: