

ASS. REG. BY:

REF:

C72/22 009526/k9

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

04

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SLK 8506E

Yr Regn: _____

01, 17

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: _____

Renault Megane

c.c

1461

Colour _____

White

A/C: _____

Insured / Std / NI / NA

Sp. Reading _____

123953

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

VFIRI-B00156-020388

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☐ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: _____

F: _____

225/45ZR17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front

R/Bal. _____

7

mm

Rear

R/Bal. _____

7

mm

L/Bal. _____

7

mm

L/Bal. _____

7

mm

D.O.A. _____

16/9/22

D.O.I. _____

28/9/2022

Survey held at _____

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

N/S/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/10

21 Lmp @ 3800

Cah

(red, 6413.90, 63%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation

S + RS. SI

Fees

Others

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

LM AUTO SOLUTION PTE LTD

**Blk 10 Sin Ming Industrial Estate Sector C,
#01-12 Singapore 575645**

Email: admin@lmautosolution.com

Tel: 90162222

VEHICLE NUM:

MAKE & MODEL:

MILEAGE:

ENGINE NUM:

CHASSIS NUM:

SLK 8506 E

RENAULT MEGANE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

DESCRIPTION OF PARTS

~~Acknowledged by Repairer~~

Signature:

Date: _____

ATTN:		• No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		QTY	PRICE	
NO.	DESCRIPTION - PARTS					
1	FRONT BONNET	Acknowledged by Repairer		1	REPAIR	
2	FRONT BUMPER	Signature: 1084	Bu	1	\$ 1,867.00	✓
3	FRONT BUMPER RETAINER LH + RH	Date: 11/10/11		2	\$ 164.00	✓
4	FRONT BUMPER BRACKET LH + RH		R	2	\$ 182.00	X
5	FRONT BUMPER REINFORCEMENT		R	1	\$ 465.00	X
6	FRONT BUMPER SPONGE		R	1	\$ 155.00	X
7	FRONT BUMPER GRILLE LH		Mj	1	\$ 126.00	✓
8	FRONT BUMPER CLIP (SET)		Mj	1	\$ 80.00	✓
9	FRONT GRILLE ASSY 701.40		Mj	1	\$ CM 858.00	✓
10	FRONT GRILLE CLIP (SET)		R	1	\$ 60.00	X
11	FRONT FENDER LH 711.80		Bu	1	\$ 963.00	✓
12	FRONT FENDER COWLING LH		CM	1	\$ 189.00	✓
13	FRONT FENDER GARNISH LH		R	1	\$ 67.00	X
14	HEADLAMP ASSY LH 1285.30		CM	1	\$ 2,986.00	✓
SUBTOTAL					\$ 8,162.00	
10% 5%					\$ 408.10	
PARTS TOTAL					\$ 7,753.90	
SPECIAL NETT				QTY	PRICE	
1	FRONT RIM LH			1	\$ R 800.00	X
SPECIAL NETT 1					\$ 800.00	
LABOUR				QTY	PRICE	
1	TO KNOCK, STRAINHTEN AND REALIGN ACCIDENT AFFECTED AREA			1	\$ 600.00	4001
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA			1	\$ 800.00	4401
3	TO RUST PROOF ACCIDENT AFFECTED AREA			1	\$ 60.00	301
4	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS			1	\$ 100.00	201
5	TO CHECK WHEEL ALIGNMENT			1	\$ 100.00	601
LABOUR TOTAL					\$ 1,660.00	
GRAND TOTAL COST					\$ 10,213.90	