

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOM	OTIVE SERVICES PTE LTD		Ref:	CS/SMR22009564/Evy3e2	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 37705		Date:	18/10/2022	
				Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHF 30L	Veh. Inspected	k	SLN 1568G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/09/22/2070	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		28/09/2022	
2.	. Vehicle Particulars & Condition					
	Make & Model	HONDA ACCORD	c.c		1997	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	MRHCR1630GP000119	Colour		SILVER	
	Odometer	50134 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/50 R16	MICHELIN		4 mm	
	L/H Front Tyre	215/50 R16	MICHELIN		4 mm	
	R/H Rear Tyre	215/50 R16	MICHELIN		4 mm	
	L/H Rear Tyre	215/50 R16	MICHELIN		4 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	27/09/2022	Inspection Dat	e	28/09/2022	
	Survey held at	KAH MOTOR CO SDN BERHAD				
		NO. 255 ALEXANDRA ROAD SINGAPORE 159937				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:		8 Work	ing Days	