LETTER OF AUTHORISATION

MHL AUTOMOBILE SERVICES BLOCK 3006 UBI ROAD 1 #01-360 SINAGPORE 408700

Dear Sir,
Accident on
Involving Vehicle NosSLB8927X
Along LOR 2 TOA PAYOH TOWARDS PIE
I/We the registered owner /driver of vehicle registration no: SLBBQZTX. have involved in the above accident. I/We hereby authorize M/S MHL AUTOMOBILE SERVICE to commence repairs of the saidvehicle forthwith. I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our solicitors to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis. I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.
I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.
Your kind co-operation in this matter will be much appreciated. Thank you.
Yours truly.

Owner's Signature (Company's stamp if applicable)

Name: YEO KOON CHENS NRIC No: 57036981D

Date: 9 Nov 2022

Allianz Insurance Singapore Pte. Ltd

Attn: Motor Claims Dept

Dear Sir/ Madam

ACCIDENT INVOLVING VEHICLE NO SUBSCIENCE SMO ALZAPALONG LORONO 2 TO A PAYON TUWARDS PIE

We understand that you are the insurer of SLB8927X vehicle.

We are instructed by the owner of motor vehicle SLB8927X to write, negotiate and settle the claim on their behalf for the abovementioned accident. We therefore propose to claim from you as follows: -

1. Cost of Repair S\$ 1180

2. Loss of Use/Rental 3 DAYS

300 S\$

LTA Search Fee/GIA Reports 3.

34.90

TOTAL

ss 1514,90.

Please let us have your reply soonest possible.

Thank you.

Yours faithfully

Signed by "the workshop"

(with chop)



Tel: (65) 6904 4584 Fax: (65) 6659 0617 Company Reg No.: 201728001G

Date:

3-Oct-2022

Invoice #: 0379

For: SJT9664B

OFFICIAL RECEIPT

Bill To:

YEO KOON CHENG

Quantity	Description	PERIOD	Amo	ount
1	LEASING OF ONE UNIT HONDA FIT- SJT9664B	current	\$	500.00
	CONTRACT AGREEMENT NO. AL-PC-CV-670			
	RENTAL PERIOD FOR 03/10/2022 - 07/10/2022			

Subtotal AMOUNT RECEIVED \$ 500.00 \$ -Balance due

Make all checks payable to AVON LEASING PTE LTD . If you have any questions concerning this invoice, kindly contact Yen Ling at 8869 8866 Thank you for your business!

BANK: DBS 003-954154- 6 / DBS PAYNOW: UEN 201728001G

This is computer-generated invoice. No signature required.

Accident	unoriginal control of the control of					
5/N (Qty Description			(55)		
2000	Parts					
			\$		794.00/6	20
1 1pc	Rear bumper Rear bumper refle	ctor	· ·		54.20 K	
3 1pc		or			195.00 K	
4 1pc	- I	retainer		\$	130.00	mer/
5 1pcs	Rear bumper spon	ge		\$	121.30	
6 1pcs		forcement		\$	235.20	
7 1pcs	Boot lid logo			\$		X
8 2pcs	Boot lid emblem "a	iltis"		\$		X
9 1pcs	Boot lid emblem "d	corolla"		\$	80.30	
10 1pcs	Boot lid rh reflecto			\$	288.70 380.10	A Charles and Company of the Company
11 lpcs	Rh taillamp			\$		THE RESERVE OF THE PARTY OF THE
12 1pcs	Rear muffler			\$	1,237.39	レン
			Total	\$	3,681.5	9
			List -25%	\$	920.4	
			Parts Sub Total	\$	2,761.1	9
	Special Nett					
	Special Nett					
1 1				Ś	50	1,00
3 Isets	Rear bumper clips			\$		0.00
3 Isets		rim clips		\$ \$		0.00
13 1sets	Rear bumper clips	rim clips	Total	\$	50	LIBERT TO STATE OF THE PARTY OF
13 1sets	Rear bumper clips	rim clips	Total		50).00 K
3 Isets	Rear bumper clips	im clips	Total	\$	50).00 K
3 1sets 4 1sets	Rear bumper clips	im clips	Total	\$	50).00 K
3 1sets 4 1sets F	Rear bumper clips Rear rh fender inner tr		Total	\$	10	0.00 K
3 1sets 4 1sets F	Rear bumper clips Rear rh fender inner tr		Total	\$	10	0.00 K
3 Isets 4 Isets F	Rear bumper clips Rear rh fender inner tr bour check wiring sytsem		Total	\$	10	0.00 \(\)
3 Isets 4 Isets F	Rear bumper clips Rear rh fender inner tr bour check wiring sytsem		Total	\$	10	0.00 \(\)
3 1sets 4 1sets F	Rear bumper clips Rear rh fender inner tr bour check wiring sytsem transfer rear bumpe	r sensor attactment.	Total	\$ \$	10	100.00 3 100.00 3
3 1sets 4 1sets F	Rear bumper clips Rear rh fender inner tr bour check wiring sytsem	r sensor attactment.	Total	\$	10	100.00 3
La To	Rear bumper clips Rear rh fender inner tr bour check wiring sytsem transfer rear bumpe R&R rear inner trim	r sensor attactment. for hot work repair.	Total	\$ \$ \$ \$	10	100.00 3 100.00 3 200.00 ×
3 1sets 4 1sets F	Rear bumper clips Rear rh fender inner tr bour check wiring sytsem transfer rear bumpe	r sensor attactment. for hot work repair.	Total	\$ \$	10	100.00 3 100.00 3 200.00
La To To To To to to the total to the total to the total to the total to	Rear bumper clips Rear rh fender inner tr bour check wiring sytsem transfer rear bumpe R&R rear inner trim carry out body cavity	r sensor attactment. for hot work repair. preservation.	Total	\$ \$ \$	10	100.00 3 100.00 3 200.00 x
3 1sets 4 1sets F	Rear bumper clips Rear rh fender inner tr bour check wiring sytsem transfer rear bumpe R&R rear inner trim carry out body cavity	r sensor attactment. for hot work repair. preservation.	Total	\$ \$ \$	10	100.00 3 100.00 3 200.00 2
3 1sets 4 1sets F	Rear bumper clips Rear rh fender inner tr bour check wiring sytsem transfer rear bumpe R&R rear inner trim carry out body cavity	r sensor attactment. for hot work repair.	Total	\$ \$ \$	10	100.00 3 100.00 3 200.00 x
La To	Rear bumper clips Rear rh fender inner tr bour check wiring sytsem transfer rear bumpe R&R rear inner trim carry out body cavity	r sensor attactment. for hot work repair. preservation.	Total	\$ \$ \$	10 10	100.00 3 100.00 3 200.00 2
La To	Rear bumper clips Rear rh fender inner tr bour check wiring sytsem transfer rear bumpe R&R rear inner trim carry out body cavity	r sensor attactment. for hot work repair. preservation.	Total	\$ \$ \$	10	100.00 3 100.00 3 200.00 2
James A sets A s	Rear bumper clips Rear rh fender inner tr bour check wiring sytsem transfer rear bumpe R&R rear inner trim carry out body cavity	r sensor attactment. for hot work repair. preservation.	Total	\$ \$ \$	10 10	100.00 3 100.00 3 200.00 x

W5 | |

1,000.00 400 Spray painting 2,700.00 Labour Total: \$ Sub Total (labour and parts): \$ 5,561.19 /473 Vehicle is at Blk 3006 Ubi Road 1 #01-360 Singapore 408700

Please arrange your surveyor to come down to survey the vehicle.

70%=294 Final 1180

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: