



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				CS3/GRB22002896/Gqy3-1	
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/GRB22002896/ys Date: 20/03/2022 26/08/2022 Code: GRB		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.	SMV 9278L	Veh. Inspected	SMX 4056H		
Policy No.		Coverage (\$)	0.00		
Claim No.		Excess (\$)	0.00		
Assign From	GABRIEL WEE CARINE KEK	Assign Date	20/03/2022 26/08/2022		
2. Vehicle Particulars & Condition					
Make & Model		c.c	0		
Engine No.	HIDDEN	Year of Reg.			
Chassis No.		Colour			
Odometer	-	Steering			
Brakes		Modification			
General					
3. Conditions of Tyres					
	Size	Make	Balance		
R/H Front Tyre			mm		
L/H Front Tyre			mm		
R/H Rear Tyre			mm		
L/H Rear Tyre			mm		
4. Description of Damages					
5. General Information					
Accident Date	19/03/2022	Inspection Date			
Survey held at	25 KAKI BUKIT ROAD 4 #06-43 SYNERGY @KB				
Repairer	SA INFINITE PAINTWORKS PTE LTD				
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					