

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 03 Oct 2022

## **Preliminary Advice**

Vehicle No	: SNE818R	Accident Date	: 23/09/2022
Make	: BMW 740LI	Policy No.	: SP2002159546-01
Assignment Date	: 29/09/2022	Excess	: S\$800.00
Date of Inspection	: 30/9/2022	Est. Duration of Repair	:4
Inspection At	: SUCCESS UNITED PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,554.10
Revised Amount	:S\$	4,135.00
Check Items (Estimated)	:S\$	16,329.50
Total	:S\$	20,464.50
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	158,000.00
COE / PARF Rebate	:S\$	90,832.00
Salvage Value	:S\$	
Margin for Repair	:S\$	67,168.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Part by part repair, as there is no 2nd hand parts available.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .