

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 63456
Date Estimated : 27/09/2022
Prepared By : Yap Mee Key

Page No. : 1 of 7

- ESTIMATE REPAIR FOR -

Chin Yoke Ching
109C Edgedale Plains
#14-133

Singapore 823109

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG6604C	WBA4H32090BP28474	28/12/2018	4201 GC	33823

DESCRIPTION	VALUE
To replace front ^{LH 1} well, bonnet and front both side panel.	5100 ✓ 6,375.00
To respray bonnet, front bumper, front both side panel and a pillar ^{both side.} ₂	4741 ✓ 5,192.00
To tow accident vehicle to PML workshop.	150.00 ✓
To supply front or rear emboss number plate. _{(Special type).} ⁰⁷	165.00 ✓
To replace radiator assembly, fan housing with fan including pressure test, bleed cooling system and conduct check for leak. (All models except 7 series).	784 826.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	X 531.00
To replace both front left and right pneumatic spring strut including reset and check function of ride level height control for proper function.	X 858.00
To conduct chassis alignment measuring check using Car-O-Liner measuring system accordance with BMW specification.	? X 531.00
To replace front windscreen glass.	X 574.00
To remove and install IU unit bracket.	X 31.00
To conduct water leak tests.	X 75.00
To check electrical.	168 ✓ 177.00
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.	X 531.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

316, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 63456
Date Estimated : 27/09/2022
Prepared By : Yap Mee Key

Page No. : 2 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG6604C	WBA4H32090BP28474	28/12/2018	4201 GC	33823

DESCRIPTION

VALUE

To replace both left and right headlights. (brusy) 795 ✓ 837.00

To replace air con condenser and air con hose including vacuum system, top up freon gas and conduct check for leak. (For all models except for 7 series). 952 ? × 1,003.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function. 168 ✓ 177.00

To carry out body cavity preservation. (Per panel).1x 442 × 118.00

Sundries. 150.00 ✓

Total Labour 1: 18,301.00

DESCRIPTION	QTY	PRIC	VALUE	
BLIND RIVET / <i>etc</i>	20	1.50	30.00	✓
C CLIP FOR PLASTIC NUT / <i>etc</i>	20	1.10	22.00	✓
RADIATOR BT	1	836.85	836.85	✓
ROCK GUARD BR	2	68.30	136.60	✓
COVER TOP X NN	1	64.25	64.25	
COVERING LOWER BT X NN	1	73.50	73.50	
RADIATOR BT Repeated	1	836.85	836.85	✗
FAN HOUSING WITH FAN 400W X NN	1	1,189.65	1,189.65	
FAN SHROUD 400W/600W X NN	1	289.00	289.00	
FRT SPRING STRUT X NN	2	530.10	1,060.20	
BONNET / <i>etc</i>	1	1,312.90	1,312.90	✓
FRT LH SIDE PANEL / <i>etc</i>	1	716.75	716.75	✓
FRT LH SIDE PANEL X NN	1	716.75	716.75	✓
FRT LH 2 SIDE PANEL BRACKET / <i>etc</i>	1	41.20	41.20	✓
FRT RH 2 SIDE PANEL BRACKET X NN	1	41.20	41.20	
FRT LH 1 SIDE PANEL BRACKET BT	1	102.95	102.95	✓
FRT RH 1 SIDE PANEL BRACKET X NN	1	102.95	102.95	
FRT LH 3 SIDE PANEL BRACKET X NN	1	41.20	41.20	
FRT RH 3 SIDE PANEL BRACKET X NN	1	41.20	41.20	
BONNET LH HINGE X NN	1	110.10	110.10	
BONNET RH HINGE X NN	1	110.10	110.10	
FRT BUMPER TOP CARRIER / <i>etc</i>	1	419.45	419.45	✓
FRT LH DEFORMATION ELEMENT / <i>etc</i>	1	112.95	112.95	✓
FRT SHOCK ABSORBER / <i>etc</i>	1	63.05	63.05	✓
LH FOG LAMP SUPPORT / <i>etc</i>	1	43.45	43.45	✓
RH FOG LAMP SUPPORT BT	1	43.45	43.45	✓
SUPPORT CENTRAL / <i>etc</i>	1	14.15	14.15	✓
LICENCE PLATE BASE ECE / <i>etc</i>	1	70.95	70.95	✓

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 63456
Date Estimated : 27/09/2022
Prepared By : Yap Mee Key

Page No. : 3 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG6604C	WBA4H32090BP28474	28/12/2018	4201 GC	33823

DESCRIPTION	QTY	PRIC	VALUE
MOUNTING SUPPORT C X NN	1	16.25	16.25
COVER LOWER PART CENTRE BR	1	44.75	44.75
FRT PANEL BUMPER PRIMED (BASIS) BR	1	1,084.65	1,084.65
FLAP TOWING EYE PRIMED X NN	1	44.35	44.35
SET MOUNTING PDC/PMA SENSOR FRT BR	1	78.20	78.20
SET MOUNTING PDC/PMA SENSOR FRT X NN	1	78.20	78.20
LH PARTIALLY OPEN GRID (SPORT/LUXUR BR	1	92.30	92.30
RH PARTIALLY OPEN GRID (SPORT/LUXUR BR	1	92.30	92.30
Closed grid, X NN	1	92.30	92.30
Closed grid, X NN	1	92.30	92.30
LH TRIM SPORT LINE	1	125.80	125.80
RH TRIM SPORT LINE	1	125.80	125.80
FINISHER ROD CENTRE (SPORT LINE) BR	1	54.15	54.15
INSERT AIR INLET MIDDLE (LINES) BR	1	153.85	153.85
FRT LH GRILLE (SPORT)	1	135.15	129.25 ✓
FRT RH GRILLE (SPORT) BR	1	131.20	129.25 ✓
CLIP	5	1.10	1.35 6.75 ✓
GAS STRUT HOOD X NN	2	127.15	254.30
STOP BUFFER X NN	2	13.05	26.10
GREEN WINDSCREEN X NN	1	817.35	817.35
COVER WINDSCREEN TOP X NN	1	38.55	38.55
BUMP STOP X NN	10	3.30	33.00
EXPANDING RIVET D=8MM X NN	20	1.10	22.00
FRONT PANEL V STRUT BT	1	120.75	120.75
FRT BUMPER LOWER MOUNT BR	1	135.10	135.10
LH HEADLIGHT BRACKET	1	15.00	15.00
RH HEADLIGHT BRACKET	1	15.00	15.00
FRONT CROSSLINK BT	1	181.10	181.10
AIR DUCT BOTTOM	1	102.40	102.40
AIR DUCT RADIATOR	1	107.50	107.50
AIR DUCT BRAKE LH BR	1	69.35	69.35
AIR DUCT BRAKE RH BR	1	69.35	69.35
FRT END SUPPORT BR	1	24.40	24.40
ADJUSTER MIS	1	5.80	5.80
FRONT ENGINE HOOD SEALING	1	39.85	39.85
LH ENGINE HOOD SEALING X NN	1	39.85	39.85
RH ENGINE HOOD SEALING X NN	1	39.85	39.85
Holder X NN	1	4.25	4.25
LH HEADLIGHT LED TECHNOLOGY	1	2,726.25	2,726.25
RH HEADLIGHT LED TECHNOLOGY	1	2,726.25	2,726.25
LH FOG LIGHT LED	1	467.55	467.55
RH FOG LIGHT LED X NN	1	467.55	467.55
DECOUPLING RING PDC TORQUE CONVERTE	4	5.30	21.20
PDC SENSOR IMPERIAL BLUE (A89) BR	4	373.90	1,495.60

Total Parts : 21,172.45

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 63456	Page No.	: 4 of 7
Date Estimated	: 27/09/2022		
Prepared By	: Yap Mee Key		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG6604C	WBA4H32090BP28474	28/12/2018	420i GC	33823

Steve (LKK)
29/9/22, 1.93p

OD- NM AL
EXCESS- ?
P/P
by Bal by
8 dys

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	18,301.00
Parts	:	21,172.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,763.14
Grand Total	:	42,236.59

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **