

Xin Yu (LKK Auto)

From: Simon Ho (LKKAuto)
Sent: Monday, 17 October 2022 11:48 AM
To: Xin Yu (LKK Auto)
Subject: Re: File Audit - SMT 1484X - CS3/AIG21011037/Tcy3-1

Dear Xin Yu,

Audit check done for SMT1484X, found boot lid spoiler not necessary to replace. Already notified Taufikh.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Xin Yu (LKK Auto) <xinyu@lkkauto.com>
Sent: Monday, 17 October 2022 11:06 am
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: File Audit - SMT 1484X - CS3/AIG21011037/Tcy3-1

Dear Simon,

File for Audit Check.

Thanks and Warmest Regards,

Xin Yu

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: XinYu@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)