

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI22009621/Uvy3m4	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	[	Date:	13/10/2022	
			(	Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMS 1971L	Veh. Inspected		JRD 8440	
	Policy No.	P10746019R00	Coverage (\$)		0.00	
	Claim No.	C10017579/CH	Excess (\$)		0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date		29/09/2022	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA 135LC	c.c		135	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	PMYUG0410F0322393	Colour		BLACK	
	Odometer	81888 KM	Steering		AFFECTED	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	70-90-17	MAXXIS		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	80-90-17	MAXXIS		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	17/09/2022	Inspection Date		30/09/2022	
	Survey held at ERZAT LEE MOTOR TRADING PTE LTD					
		25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: