

(08/14/13) wef

ASS. REC. BY: Marcus

REF:

CS/ICS 22009629/Uny3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/10/22 4/56400 7 days. informed Susan.
(Red, 7781.40, 55%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 11/10/22

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$ 6400)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

[➤ Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Company

Owner ID:

196N

Vehicle Details

Vehicle No.:

GBL1442P

Vehicle to be Exported:

No

Intended Deregistration Date:

28 Sep 2022

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE DX 2.8 AUTO

Primary Colour:

Silver

Manufacturing Year:

2021

Engine No.:

1GD8688506

Chassis No.:

GDH2011055635

Maximum Power Output:

-

Open Market Value:

\$33,728.00

Original Registration Date:

19 Mar 2021

First Registration Date:

19 Mar 2021

Transfer Count:

2

Actual ARF Paid:

\$1,687.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

18 Mar 2031

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$40,999.00

COE Rebate Amount:

\$34,705.00

Total Rebate Amount:**\$34,705.00**

The information contained herein is correct as at 28 Sep 2022

OK



New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement

Sell it yourself! Advertise it at just

\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

C180K 1.6A, 100% Loan by GV CARS FINANCING



Secured Loan by In house finance, Warranty packages and services available.
GV Automobile Centre StarAd

• Free VICOM evaluation
 • Free grooming and 6 months maintenance
 • In-house workshop ensures quality service
 • Member of SVTA and hire purchase association
 • 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Sort by 20 results/page

12 vehicles



Toyota Hiace dx 2.8

Any Category

Advanced Search

Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota	Hiace dx 2.8	Any	Any	2021	Any	Any	Any	Available
	Toyota	Hiace 2.8A DX	\$94,300	\$10,730 /yr	14-Jul-2021	2,754 cc	36,441 km	Van	Available
	Fuel Type: Diesel								
	Best deals with us. Low mileage and smooth transmission. 3 month warranty, fully serviced before handover + additional 2 free servicin...								
	Skylink Auto Pte Ltd								
	Posted: 26-Sep-2022								
	Toyota	Hiace 2.8A DX	\$95,800	\$10,900 /yr	14-Jul-2021	2,754 cc	35,143 km	Van	Available
	Fuel Type: Diesel								
	Best deals with us. Low mileage and smooth transmission. 3 month warranty, fully serviced before handover + additional 2 free servicin...								
	Skylink Auto Pte Ltd								
	Posted: 26-Sep-2022								
	Toyota	Hiace 2.8A DX	\$88,999	\$10,490 /yr	24-Mar-2021	2,754 cc	-	Van	Available
	Fuel Type: Diesel								
	New Condition. 3 Months Warranty And Free Servicing. 100% Loan Can Submit. Bank / In House Loan Support. Low Interest Rate. Cust...								
	ABS Bus Pte Ltd								
	Posted: 26-Sep-2022								
	Toyota	Hiace 2.8A DX	\$89,800	\$10,560 /yr	31-Mar-2021	2,754 cc	41,200 km	Van	Available
	Fuel Type: Diesel								
	Feel free to arrange for viewing!								
	Posted: 26-Sep-2022								
	2022 Toyota Hiace Diesel 2.8A Brand New (For Lease)								
	Brand New Hiace 2.8A (2022) For Lease! Road tax,insurance,servicing,replacement vehicle,24hrs towing etc all covered.								
	More info about this vehicle								
	Toyota	Hiace 2.8A DX	\$91,800	\$10,800 /yr	30-Mar-2021	2,754 cc	-	Van	Available
	Fuel Type: Diesel								
	Still under warranty and free servicing. Toyota Hiace 5 door auto with rear aircon. Nice number plate. Super low mileage. Like new one....								
	ABS Bus Pte Ltd								
	Posted: 23-Sep-2022								
	Toyota	Hiace 2.8A DX	\$90,800	\$10,820 /yr	18-Feb-2021	2,754 cc	47,123 km	Van	Available
	Fuel Type: Diesel								
	Best deals with us. Low mileage and smooth transmission. 3 month warranty, fully serviced before handover + additional 2 free servicin...								
	Skylink Auto Pte Ltd								
	Posted: 18-Sep-2022								
Compare									

Compare



Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J

liusbro@gmail.com

Tel: 67411730

ESTIMATE

Name: ECICS Limited

Address Motor Claims Department

10 Eunus Road 8 #09-04A

Singapore Post Centre Singapore 408600

Ref Date:

Ref No:

Vehicle No:

Model / Make:

Capacity: 2754 cc

29-09-2022

GBL1442P220924

GBL1442P

Toyota Hiace

DX 2.8 Auto

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear	Tailgate <i>Body rd</i>	\$ 2,051.60	1	\$ 2,051.60		—
2		Tailgate Lock <i>Ym</i>	\$ 264.70	1	\$ 264.70		—
3		Tailgate Lock Outer Garnish <i>CNE</i>	\$ 137.60	1	\$ 137.60		—
4		Tailgate Weatherstrip <i>TW</i>	\$ 391.20	1	\$ 391.20		— 361.20
5		Tailgate Inner Trim Board <i>Trn</i>	\$ 197.40	1	\$ 197.40		—
6		Tailgate Inner Trim Board Clips <i>nn</i>	\$ 5.50	16	\$ 88.00		X
7		Tailgate Number Plate & Base <i>scn</i>	\$ 48.00	1	\$ 48.00	SN	40 s/n
8		Tailgate Number Plate Lamp Outer Garnish <i>CNE</i>	\$ 346.50	1	\$ 346.50		—
9		Tailgate Number Plate Lamp <i>nn</i>	\$ 138.60	2	\$ 277.20		X
10		Tailgate Inner Lock <i>Replaced</i>	\$ 359.00	1	\$ 359.00		X
11		Tailgate "HIACE" Emblem <i>neu</i>	\$ 105.00	1	\$ 105.00		— 72.20
12		Tailgate "Toyota Logo" Motif <i>neu</i>	\$ 167.00	1	\$ 167.00		— 68.50
13		Tailgate "70 KM/H" <i>neu</i>	\$ 15.00	1	\$ 15.00	SN	10 s/n
14		Tailgate "8 PAX" Stricker <i>neu</i>	\$ 15.00	1	\$ 15.00	SN	10 s/n
15		Tailgate Windscreen Moulding <i>NS</i>	\$ 219.00	1	\$ 219.00		X
16		Tailgate Windscreen Sealant <i>neu</i>	\$ 50.00	1	\$ 50.00	SN	40 s/n
17		Tail Lamp <i>CNE</i>	\$ 365.10	2	\$ 730.20		—
18		Tail Lamp Panel Rh <i>Body rd</i>	\$ 674.00	1	\$ 674.00		— 408.20
19		Exhaust Pipe <i>R</i>	\$ 971.10	1	\$ 971.10		X
20		Exhaust Pipe Mounting <i>nn</i>	\$ 42.50	2	\$ 85.00	SN	X
21		Spare Tyre Carrier <i>Best</i>	\$ 345.20	1	\$ 345.20		—
22		End Panel Inner <i>Body rd</i>	\$ 936.20	1	\$ 936.20		— 801
23		End Panel Outer <i>Body rd</i>	\$ 566.10	1	\$ 566.10		— 455
24		End Panel Sealant <i>neu</i>	\$ 50.00	1	\$ 50.00	SN	— s/n
25		Bumper <i>2.1</i>	\$ 599.30	1	\$ 599.30		—
26		Bumper Clips 1 set <i>neu</i>	\$ 48.00	1	\$ 48.00	SN	40 s/n
27	4215	Bumper Bracket <i>@ 30x4 = 120 Best</i>	\$ 292.00	4	\$ 404.00		— 120
28		Bumper Reverse Sensor <i>Trn</i>	\$ 220.00	1	\$ 220.00	SN	200 s/n
29		Bumper Step Panel <i>Best</i>	\$ 262.30	1	\$ 262.30		—
30		Floor Panel Beam <i>R</i>	\$ 277.80	1	\$ 277.80		X
31		Floor Panel Top Wooden Board <i>SC</i>	\$ 450.00	1	\$ 450.00		X
C/F Balance --->					\$ 11,351.40		

Not Affected
neu

30/9/22

1/5 \$ 6400
after repair
7 days



7220.9
252
5415.67
390
2280
6684



liusbro@ymail.com

Tel: 67411730

DX 2.8 Auto