

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile					
	SINGAPORE CIVIL DEFENCE FORCE (MHA05) Ref: CS/SCD22009631/Eqy3m4					
	91 UBI AVE 4 SINGAPORE 4088 SINGAPORE 4088			Date:	07/11/2022	
				Code:	SCD	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	YN 4126A	Veh. Inspected		SJZ 8050Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	2022 - 89	Excess (\$)		0.00	
	Assign From	RALF TAY	Assign Date		29/09/2022	
2.	2. Vehicle Particulars & Condition					
	Make & ModelMERCEDES BENZ E300Ec.c1991					
	Engine No.	HIDDEN	Year of Reg.		2022	
	Chassis No.	W1K2130532B044110	Colour		BLACK	
	Odometer	9596 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.		Condition	ons of Tyres			
		Size	Make		Balance	
	R/H Front Tyre	275/35 R19	GOODYEAR		5 mm	
	L/H Front Tyre	275/35 R19	GOODYEAR		5 mm	
	R/H Rear Tyre	275/35 R19	GOODYEAR		5 mm	
	L/H Rear Tyre	275/35 R19	GOODYEAR		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	20/09/2022	Inspection Date	е	25/10/2022	
	Survey held at	CYCLE & CARRIAGE INDUSTRI	IES PL			
	188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)					
5a.		Re	emarks			
		N WAS CONDUCTED ON A"WIT E TO YOUR INSTRUCTIONS, WI				
5b.		Estimate I	Days of Repair			
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		3 Worki	ng Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 8050Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER BOTTOM PANEL (SN)	CUT	286.08	286.08
1	REAR BUMPER BOTTOM PANEL GARNISH (SN)	CUT	308.33	308.33
			594.41	594.41
	<u>LABOUR</u>			
	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT.		380.00	380.00
	REMOVE & REPAIR REAR BUMPER.		1,440.00	960.00
	RESPRAY REAR BUMPER.		1,000.00	800.00
			2,820.00	2,140.00
	GRAND TOTAL		3,414.41	2,734.41

RECOMMENDED COST OF REPAIRS 2,734.41

Report Ref No. CS/SCD22009631/Eqy3m4



Automotive Assessor

X: S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 21/09/2022 17:50 (SGT) Reported by Date of Accident 20/09/2022 08:35 (SGT) Exact Location of Accident Singapore Additional Location Information Lornie road towards PIE Tuas Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Mercedes

Vehicle Registration Number SJZ8050Y

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner DAIMLER SOUTH EAST ASIA PTE LTD Company Reg No 1XXXXX355E Email Address Thomas.chan@mercedes-benz.com Mobile Phone No (Phone) +65-68498587 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer

Model E300e Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Commercial vehicle Transmission Auto CC 1991

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Policy Number / Cover Note Number 999996111

DRIVER

Name of Driver **CHAN KAM CHUEN** NRIC No SXXXX441Z Date Of Birth 21/10/1967 Occupation Indoor

Date Of Driving Pass 31/07/1989 Driving experience 33 YEARS AND 2 MONTHS Gender Mobile Number (Phone) +65-90993500 Alt. Phone Number Email Address Thomas.chan@mercedes-benz.com Address 70 Hougang ave 7 Address complement #05-08 Postcode 538804 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? Nο Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Raining Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? Yes

Was the accident reported to the police?

Police Station Name

Ang Mo Kio Division Headquarters

Police Station Phone No

(Phone) +65-18002180000

(Fax) +65-64814246

Police Station Address

51 Ang Mo Kio Avenue 9 Singapore 569784

Was notice of intended Prosecution given?

No

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

CAR ACCIDENT HAPPENED ALONG LORNIE ROAD AT APPROX 0835AM ON 20 SEPT 2022 AT TRAFFIC JUNCTION (RHS MACRITCHIE RESERVIOR) BEFORE MOVING UP TOWARDS DIRECTION OF PIE TUAS. BETWEEN 2 VEHICLES YN4126A AND SJZ8050Y WAS STATIONARY AT TRAFFIC JUNCTION WHEN YN4126A HIT THE REAR OF SJZ8050Y.NO ONE WAS INJURED AND BOTH VEHICLES SUSTAIN NO VISIBLE DAMAGES.WAS AGREED THAT SJZ8050Y WILL BE SENT TO SERVICE CENTRE FOR CHECKS ON NON -VISIBLE DAMAGES. WEATHER CONDITION :HEAVY RAIN . NAME OF DRIVER OF YN44126A: MOHAMMAH SOLEHAN BIN SAMION .LICENCE NUMBERS: T0227498H . VEHICLE FRONT PASSENGER OF YN4126A: LAU CHUNG YAN BERTRAND .LICENSES NOS: S9513738E.

ATTACHMENT(S)

Are accident photos available for attachment?

Yes
Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN4126A
Vehicle Manufacturer	Isuzu
Vehicle Model	NJR85AUE6W
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Commercial vehicle
Name of Driver	MOHAMMAD SOLEHAN BIN SAMION
NRIC No	TXXXX498H
Contact Number	(Phone) +65-85184350
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurence Association of Singapore (GA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that


- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (ii) Investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents. (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


		Witnessed By Reporting Officer Muhammad Sumardi Bin Mohd Affan
Policyholder's Signature / Date &	Driver's Signature (If driver is not the policyholder) / Date	Witnessed by Reporting Centre
Time	& Time	Personnel

Sketch Plan



Mohd Affandi

s are true in every r	respect.			
	s are true in every (s are true in every respect.	s are true in every respect.	s are true in every respect. Witnessed I







1 of 2

Report No. F/20220920/7077

POLICE REPORT (NP299)

Police Station Of Origin Ang Mo Kio Division HQ 51 Ang Mo Kio Avenue 9 SINGAPORE 569784 Tel No:1800-2180000

Date/Time Report Made	Vide Re	Vide Report No.		Station Diary No.
20/09/2022 18:37				
Name Of Informant	Address	Š.		
CHAN KAM CHUEN	70 HOU	GANG AVE	ENUE 7 #05-08 S	INGAPORE 538804
ID Type / ID No.	Contact	No.	All Maries of Wildows State Control Michigan	
NRIC NO / \$1809441Z	Home/Office: Mobile:			
			90993500	
Nationality	Email A	ddress		
SINGAPORE CITIZEN	Thomas	.chan@Me	rcedes-benz.com	
Occupation	Sex	Age	Date of Birth	Race
Sales manager	Male	54	21/10/1967	Chinese
Institution/School Name	Language English			
Date/Time Of Incident	Location Of Incident			
20/09/2022 08:35 - 20/09/2022 09:00	70 HOUGANG AVENUE 7 #05-08 SINGAPORE 538804			
Drief details				

Brief details.

Car Accident happened along Lornie road at approx 0835am on 20 Sept 2022 at traffic junction (RHS Macritchie reservior) before moving up towards direction of PIE Tuas.

Between 2 vehicles YN4126A and SJZ8050Y was stationary at traffic junction when YN4126A hit the rear of SJZ8050Y.

No one was injured and both vehicles sustain no visible damages.

Was agreed that SJZ8050Y will be sent to service centre for checks on non-visible damages.

Weather condition: heavy rain.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass No signature is required.		
Signature Of Interpreter: Not applicable	Date/Time: 20/09/2022 18:37		
Officer In-Charge Of Case:	Classification Of Case:		





2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20220920/7077

Name of Driver of YN4126A: Mohammah Solehan Bin Samion

Licence numbers: T0227498H

Vehicle front passenger of YN4126A: Lau Chung Yan Bertrand

Licence nos.: S9513738E

Victim	XIVOCON TO THE TAXABLE DEPOSIT OF TAX		
Person Name	CHAN KAM CHUEN	Who control of	
ID Type	NRIC NO	ID No	S1809441Z
Gender	Male	Age	54
Race	Chinese	Language	English
Occupation	Sales manager	Address	70 HOUGANG AVENUE 7 #05 08 SINGAPORE 538804
Mobile No	90993500	Is Informant A Victim?	Yes

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass No signature is required.		
Signature Of Interpreter: Not applicable	Date/Time: 20/09/2022 18:37		
Officer In-Charge Of Case:	Classification Of Case:		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJZ 8050Y

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315



