



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS/ASM22009639/Ucy3m4 Date: 25/10/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3177M	Veh. Inspected	SLM 7244G
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M04BWL	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	29/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA AXIO	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	NRE1610022981	Colour	BLACK
	Odometer	412897 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	FIRENZA	7 mm
	L/H Front Tyre	185/60 R15	FIRENZA	7 mm
	R/H Rear Tyre	185/60 R15	TOURADOR	7 mm
	L/H Rear Tyre	185/60 R15	TOURADOR	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/09/2022	Inspection Date	30/09/2022
	Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	