08/11/13) wef REF: (S CTI2)	2009656 Dny3
ASS. REC. DT.	GNMENT
From: Date:	Veh No: Regn: July / 2016 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	/11
To Inspect Vehicle No:	2
at Workshop m/s	Sp.Reading 102296 A/C: Insured / Std / NI / NA
of	The state of the s
Insured:	Eng/No: 30139602 B37 C15A C/No: 26A2B32080 V791332
Policy No.	Gen. Cond: Good / Fair / Poor / Burnt
Claims No.	Steering: Inorder / Jammed / Leaked / Burnt-or
Sum Insured: Excess:	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Modi: Nil / S/Rim / STD A/Rim or
Make of Veh:	
	Tyre Size: F: 205 60 7216
(Policy Condition) Pomerly: The yell had commenced its N/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Remark: The veh had commenced its repair at the time of inspection.	TOYO/YOKO or Goody.~
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. S mm R/Bal. S mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal mm L/Bal mm
Est. Repairs: 5 days Res.: Yes or No	D.O.A. 28 09 222 D.O.I. 04/10/222 Survey held at QS ang AMK
Lum Sum: 3 Val.: Yes or No	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	P1 1 (1)
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction China Taping GBB 9465	5 days 7 /4 - ;
(Red. 4 56	,476,86, 87°(°)
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 5
1) \2\\\\23 : Final Report	Resurvey No. of Trip: 1 Survey Fee: Transportation:
Add Fe	e: : Site Insp (\$)s + Rss
2)	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 8500)	:Weekend (\$)
	TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	771J
Vehicle No.:	SNA4075L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Sep 2022
Vehicle Make:	B.M.W.
Vehicle Model:	216D ACTIVE TOURER D/AB LED
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	30139602B37C15A
Chassis No.:	WBA2B32080V791332
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$27,158.00
Original Registration Date:	29 Jul 2016
First Registration Date:	29 Jul 2016
Transfer Count:	3
Actual ARF Paid: Intended PARF Rebate Details	\$20,022.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jul 2026
PARF Rebate Amount: Intended COE Rebate Details	\$13,014.00
COE Expiry Date:	28 Jul 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$57,501.00
COE Rebate Amount:	\$20,288.00
Total Rebate Amount:	\$33,302.00

The information contained herein is correct as at 29 Sep 2022



Extended Lifetime Warranty Included! 1 And Only High Spec With Head Up Display In The Entire Market. Extremely Rare! Regularly Servi... Hua Yang Credit Pte Ltd

Posted: 24-Sep-2022



RMW 2 Series 216d Gran

\$17,460 /vr \$74,800

07-Apr-2016

1,496 cc

197.800 km

MPV

Available

Tourer Fuel Type: Diesel (Euro 5 Engine and Above)

Cheapest in market. Accident free, Beauty white unit with in-car front and back cameras. Suitable For All Ages, Idea For New / Fresh / Y...

CONSIGNMENT

This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More

Posted: 25-Sep-2022



BMW 2 Series 216d Gran

\$76,800

\$17,940 /yr

13-Apr-2016

1.496 cc

MPV

Available

Tourer Luxury Sunroof Fuel Type: Diesel (Euro 5 Engine and Above)

1 year extended warranty by Sgcarmart premium dealer with official warranty certificate, high loan available, free servicing, accident fre...

This car comes with 6-mth Sgcarmart Warranty - the best protection for your car, Learn More

PREMIUM AD

CARWAY

Posted: 24-Sep-2022



BMW 2 Series 216d Active

\$70,800

\$16,880 /yr

04-May-2016

126,800 km Hatchback Available

Tourer

Fuel Type: Diesel (Euro 5 Engine and Above)

Full tank diesel at least 800km. New carplate. Well taken/ maintained, Pristine condition. Interest rate from 2,48%, Trade in welcome. M...

PREMIUM AD

Car (S) Pte Ltd

Posted: 22-Sep-2022



BMW 2 Series 216d Gran

\$72,800

\$16,460 /yr

27-May-2016

1,496 cc 126,000 km MPV

Available

Tourer Luxury

Fuel Type: Diesel (Euro 5 Engine and Above)

100% loan approval! Elegant pearl white. Well maintained by previous owner. Well kept interior. No repair require. Seeing is believing. Fl...

Posted: 23-Sep-2022



BMW 2 Series 216d Gran

\$75,800

\$17,230 /yr

01-Jun-2016

1,496 cc 87,000 km MPV

Available

Tourer Luxury

Fuel Type: Diesel (Euro 5 Engine and Above) 2 owners, GT luxury 7-seater unit, PML agent unit, agent maintained, wear & tear changed, 100% loan available, accident free, road tax...

Posted: 01-Sep-2022



BMW 2 Series 216d Gran

\$77,800

\$17,020 /yr

28-Jul-2016

1.496 cc

109,000 km

Available

Tourer Luxury

Fuel Type: Diesel (Euro 5 Engine and Above)

Beautifully Maintained! Sporty White With Black Interior! Warranty And Grooming Packages Avail! Trade-In Your Current Car! Attractives...

This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More

PREMIUM AD

G2 Auto Trading Pte Ltd

Posted: 18-Sep-2022



BMW 2 Series 216d Active Tourer

\$73,800

\$16,620 /yr

01-Aug-2016

1,496 cc

121.563 km

Hatchback

Available

Fuel Type: Diesel (Euro 5 Engine and Above)

Great saving on road tax and fuel consumption! Black exterior on black interior! Original paintwork and condition! Zero mishap! Low mile...

This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More

PREMIUM AD

Le Motor Enterprise

Tourer

Posted: 22-Sep-2022



BMW 2 Series 216d Active

\$74,800

\$16,600 /vr

25-Aug-2016

1,496 cc

90,000 km

Hatchback

Available

Fuel Type: Diesel (Euro 5 Engine and Above)

Powerful twin scroll turbo with excellent fuel consumption. Accident free with original paintwork. Clean and beautiful interior. Trade in we...

Posted: 19-Sep-2022



BMW 2 Series 216d Gran Tourer Luxury

\$16,890 /vr \$78,800

01-Sep-2016

1.496 cc

105 000 km

MPV

Available

Fuel Type: Diesel (Euro 5 Engine and Above)

1 owner agent unit! Popular MPV unit to suits your daily usage with low fuel! Responsive and powerful engine! Ultimate driving experien...

This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More

JY Auto Pte Ltd

Posted: 10-Sep-2022

C. S. ONG AUTO PTE LTD

10, ANG MO KIO IND PARK 2A, #02-16 AMK AUTOPOINT, SINGAPORE 568047

TEL: 6484 1933 | FAX: 6484 1922

E-Mail: csongauto@yahoo.com.sg

To:

CHINA TAIPING

Att:

Motor Claims Dept

ACCIDENT INVOLVING GBJ2892C [YOUR INSURED] & SNA4075L [OUR CLIENT] ON 28/09/2022.

ESTIMATED REPAIR COSTS FOR SNA4075L

MODEL: BMW 216i

QTY	PARTS	AMOUNT	
VII		234	8.50
2PCS	HEAD LAMP LH / RH @ \$4,984.00 EACH OSHIM HIS MONLY COZIC	\$ 9,968.00	الما
2PCS	HEAD LAMP LOWER BRACKET LH / RH @ \$249.00 EACH	\$ 498.00	*
2PCS	HEAD LAMP TOP BRACKET LH / RH @ \$439.00 EACH	\$ 878.00	×.
1PC	FRONT BUMPER disture 854.50	\$ 1,601.00	1
2PCS	FRONT BUMPER GRILLE LH / RH @ \$495.00 EACH		\times
2PCS	FRONT BUMPER GRILLE CHROME LH / RH @ \$395.00 EACH	\$ 790.00	X 224.0
2PCS	FRONT BUMPER FOG LAMP LH / RH @ \$453.10 EACH HH	\$ 906.20	X
2PCS	FRONT BUMPER FOG LAMP GARNISH LH / RH @ \$285.00 EACH	\$ 570.00	X
1PC	FRONT BUMPER FOG LAMP WIRE HARNESS	\$ 1,930.00	X
1PC	FRONT BUMPER LOWER GRILLE	\$ 690.00	X
1PC	FRONT BUMPER NO. PLATE BASE	\$ 202.80	X
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$195.00 EACH	\$ 390.00	*
4PCS	FRONT BUMPER SENSOR @ \$389.00 EACH	\$ 1,556.00	*
1SET	FRONT BUMPER SENSOR HOLDER	\$ 100.00	*
1PC	FRONT BUMPER SENSOR WIREHARNESS	\$ 2,995.00	×
1PC	FRONT BUMPER SPONGE town 192.00	\$ 423.00	1
1PC	FRONT REINFORCEMENT BAR	\$ 1,992.00	X
1PC	FRONT SUPPORT PANEL		*
1PC	FRONT SUPPORT PANEL FRONT GARNISH	\$ 892.00	X
1PC	TAILGATE Dacks	\$ 3,895.00	1
1PC	TAILGATE LOGO HLL 105.W	\$ 124.00	4
1PC	TAILGATE M EMBLEM HILL 98.20	\$ 154.00	4
2PCS	TAILGATE LAMP LH / RH @ \$1,049.00 EACH - S many cool		1 .
1PC	TAILGATE SWITCH CALLE HH	\$ 342.00	Pronx
1PC	TAILGATE LOCK HM 399.40	\$ 410.00	X
1PC	TAILGATE WEATHER STRIP SAL	\$ 481.00	X
1PC	TAILGATE INNER TRIM	\$ 994.00	X
2PCS	TAILGATE HINGE LH / RH @ \$210.00 EACH	\$ 420.00	4 (.
2PCS	TAILGATE NO. PLATE LAMP LH / RH @ \$194.00 EACH	\$ 388.00	-
2PCS	TAILGATE HYDRAULIC DAMPER LH / RH @ \$1,890.00 EACH	\$ 3,780.00	X
1PC	REAR WINDSCREEN GLASS MOULDING Have 161.20	\$ 332.00	

	PARTS SUM:	\$ 59,638.80
SET	REAR FENDER INNER TRIMBOARD CLIPS	\$ 100.00
PCS	REAR FENDER INNER TRIMBOARD LH / RH	\$ 1,244.00
IPC	REAR END PANEL TOP GARNISH	\$ 493.00
IPC	REAR END PANEL	\$ 2,014.50
IPC	REAR KEYLESS BUZZER CONC	\$ 274.00
PC	REAR KEYLESS SENSOR WALL 263.00	\$ 395.00
PC	REAR REINFORCEMENT BAR Deval 655.00	\$ 1,829.00
PC	REAR BUMPER SPONGE	\$ 423.00
PC	REAR BUMPER LOWER LID HS	\$ 849.00
PCS	REAR BUMPER REFLECTOR LH / RH @ \$194.00 EACH	\$ 388.00
PC	REAR BUMPER TOWING COVER: destand 12 93.70	\$ 154.30
PC	REAR BUMPER SENSOR WIREHARNESS SAC	\$ 2,995.00
PC	REAR BUMPER TOP CHROME	\$ 483.00
SET	REAR BUMPER SENSOR O-RING 3V	\$ 50.00
SET	REAR BUMPER SENSOR HOLDER SVC 360.00	\$ 100.00
PCS	REAR BUMPER SENSOR @ \$389.00 EACH 2 PC DC 2 PC HA	\$ 1,556.00
PC	REAR BUMPER AS THE RETAINER LH / RH @ \$195.00 EACH	\$ 2,431.00 390.00

LABOUR & SPECIAL NETT ITEMS

9376.80

10% 8,439.12

*	TO SUPPLY FRONT BUMPER CLIPS He	\$ 50.00 20 /-
*	TO SUPPLY FRONT BUMPER LOWER GRILLE CLIPS HH	\$ 50.00 ×
*	TO SUPPLY TAILGATE INNER TRIM CLIPS HH	\$ 50.00 ×
*	TO SUPPLY TAILGATE LAMP CLIPS HH	\$ 50.00 🔀
*	TO SUPPLY TAIL LAMP CLIPS HA	\$ 50.00 >
*	TO SUPPLY REAR BUMPER CLIPS Have	\$ 50.00 20/~
*	TO SUPPLY REAR END PANEL SEALANT	\$ 80.00 🔀
*	TO SUPPLY REAR END PANEL TOP GARNISH CLIPS	\$ 50.00 >
*	TO SUPPLY REAR WINDSCREEN SEALANT LLC 80.00	\$ 80.00 40/
*	TO SUPPLY REAR WINDSCREEN DAMPING SEAL	\$ 30.00 %
*	TO SUPPLY REAR WINDSCREEN INNER SEAL	\$ 80.00 ⊀
*	TO SUPPLY FRONT & REAR NO. PLATE & GARNISH	\$ 200.00 ×
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	\$ 200.00 HH
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	\$ 1,200.00300 -
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	\$ 1,200.00

PARTS LESS 5%: \$ 2,981.94

PARTS TOTAL: \$ 56,656.86

*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	\$ 1,600.006001-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	\$ 1,400.00 600
*	TO TUFF COAT DAMAGED AREAS	\$ 200.00 40 -
*	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	\$ 500.00 1201-
*	TO RNR AIRCON CONDENSER AND TOP UP GAS	\$ 200.00
*	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$ 200.00 60 -
*	TO RNR FRONT BUMPER SENSOR TO FACILITATE REPAIRS	\$ 150.00 40/-
*	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	\$ 150.00 46 -
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00 30 -
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00

LABOUR & S/N TOTAL: \$ 8,320.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 64,976.86

10,699.12

04/16/2022 @ 1300m HA ANDUM 1/2011 5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: