



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No. 0				
			Document Date 07/10/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	21/06/2017	SLP8723T	0	17764	75/DS/SLP8723T
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFB29F3002010352		2NRX148917	60	Ng Mei Yen	30/09/2022 8.00		07/10/2022 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SLH7000U ACC DATE:29/09/22 DRIVE IN:29/09/22 DATE-IN: DATE SURVEY:30/09/22 NO OF REPAIR DAYS:4 DAY BY: TAUFILK LKK				50.00	
2	L	BP-LPO SUPPLY REAR REGN PLATE (PO#)	0263			80.00	
3	S	BP-SUBLET CHECK WIRING & CONDUCT LEAK TEST				180.00	
4	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00	
5	S	BP-SUBLET DRILL HOLE & INSTALL REVERSE SENSOR				180.00	
6	S	BP-SUBLET REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA				1440.00	
7	S	BP-SUBLET RESPRAY ACC AFF AREA				1180.00	
8	S	BP-SUBLET SUPPLY SEALANT (NETT)				100.00	
9	1	K52159-0U908 COVER, RR BUMPER, L	1.00	565.60		565.60	
10	2	K52155-0D090 SUPPORT, RR BUMPER S	1.00	25.00		25.00	
11	3	S52161-0K040 PIECE, RR BUMPER	10.00	4.50		45.00	
12	4	K64401-0D160 PANEL SUB-ASSY, LUGG	1.00	852.90		852.90	
13	5	K75442-0D250 PLATE, LUGGAGE COMPT	1.00	49.40		49.40	
14	6	K90975-T2006 EMBLEM, SYMBOL	1.00	57.50		57.50	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		
					Lubrication/Fluid		
			Others		Amount Due		

Customer Copy



Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462. Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept				S1000003 / ICCI1		M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
				Document No.					
				0					
				Document Date					
07/10/2022									
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	NSP151R	CEXRKT Q1	21/06/2017	SLP8723T	0	17764	75/DS/SLP8723T		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
MHFB29F3002010352		2NRX148917	60	Ng Mei Yen	30/09/2022 8.00		07/10/2022 18.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
15	7	K75444-0D460 PLATE, LUGGAGE COMPT				1.00	38.50		38.50
16	8	SPC507-47009 00 BACK SENSOR (PRIMER)				1.00	167.50		167.50
For & on behalf of		Customer's Signature		Charge Summary			Total		
Borneo Motors (Singapore) Pte Ltd							5,191.40		
		Please acknowledge receipt of vehicle					GST 7.00%		
				Parts 1,801.40			363.40		
				Labour 50.00					
				Sublet 3,340.00			Less 0.00		
				Lubrication/Fluid 0.00					
				Others 0.00			Amount Due 5,554.80		

Customer Copy