



Borneo Motors



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details			
THIRD PARTY CLAIM				S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd			
				Document No.		3 Media Close			
				0		#01-03/06			
				Document Date		Singapore 138498			
				29/09/2022		Work: 65703925			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	NSP151R	CEXRKT Q1	21/06/2017	SLP8723T	0	17764	75/DS/SLP8723T		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
MHFB29F3002010352		2NRX148917	60	Ng Mei Yen	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount			
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SLH7000U ACC DATE:29/09/22 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				✓ 50	100.00		
2	B	BP-LAB2 CHECK WIRING & CONDUCT LEAK TEST				✓	180.00		
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				✓	180.00		
4	B	BP-LAB2 DRILL HOLE & INSTALL REVERSE SENSOR				✓	180.00		
5	Z	BP-SLANT SUPPLY SEALANT (NETT)				✓	100.00		
6	L	BP-LPO SUPPLY REAR REGN PLATE (PO#)				bt	80.00		
7	B	BP-LAB2 R/I REAR BOOT INTERIOR TRIMMING				nn X	720.00		
8	B	BP-LAB2 REPL ACC AFF AREA 770 STRAIGHTEN & PANEL BEAT ACC AFF AREA				1440	2880.00		
9	B	BP-RES2 RESPRAY ACC AFF AREA 2540				1180	2950.00		
10	1	K52159-0U908 COVER, RR BUMPER, L/	1.00	565.60		de	565.60		
11	2	K52023-0D100 REINFORCEMENT SUB-AS	1.00	360.10		nn X	360.10		
12	3	K52155-0D090 SUPPORT, RR BUMPER S	1.00	25.00		de	25.00		
13	4	K52156-0D080 SUPPORT, RR BUMPER S	1.00	25.00		nn X	25.00		
14	5	K52591-0D250 SEAL, RR BUMPER SIDE	1.00	65.00		nn X	65.00		
							3980.60		
For & on behalf of			Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd							Taufik 97495749		
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		NP 30/9/22 01130 Resuming before paint Taufik@thuan.com Less 4 days.		
							Amount Due		

Customer Copy



Borneo Motors

chcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE

Account Details	Account No.	Acknowledged by Repairer	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Signature:	M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925
	Document No.	Date:	
	0		
	Document Date		
	29/09/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	21/06/2017	SLP8723T	0	17764	75/DS/SLP8723T
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MHFB29F3002010352	2NRX148917	60	Ng Mei Yen	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
15	6	K52592-0D250 SEAL, RR BUMPER SIDE	1.00	65.00		65.00	mm x
16	7	T52161-16010 PIECE, RR BUMPER	10.00	4.50		45.00	rec 48.00
17	8	K58307-0D250 PANEL SUB-ASSY, BODY	1.00	775.70		775.70	mm x
18	9	K64401-0D160 PANEL SUB-ASSY, LUGG	1.00	852.90		852.90	bt 852.90
19	0	K64461-0D130 WEATHERSTRIP, LUGGAG	1.00	190.10		190.10	X 190.10
20	1	K64503-0D040 ARM SUB-ASSY, LUG CO	1.00	65.00		65.00	mm X 65.00
21	2	K64503-0D040 ARM SUB-ASSY, LUG CO	1.00	65.00		65.00	X 65.00
22	3	K64610-0D080 LOCK ASSY, LUGGAGE C	1.00	101.80		101.80	X 101.80
23	4	K75442-0D250 PLATE, LUGGAGE COMPT	1.00	49.40		49.40	rec 49.40
24	5	K90975-T2006 EMBLEM, SYMBOL	1.00	57.50		57.50	rec 57.50
25	6	K75444-0D460 PLATE, LUGGAGE COMPT	1.00	38.50		38.50	rec 38.50
26	7	K81550-0D550 LAMP ASSY, RR COMBIN	1.00	345.90		345.90	X 345.90
27	8	K81560-0D550 LAMP ASSY, RR COMBIN	1.00	345.90		345.90	X 345.90
28	9	T81270-0D120 LAMP ASSY, LICENSE	1.00	70.80		70.80	mm X 70.80
29	0	K81580-0D190 LAMP ASSY, RR, RH	1.00	205.00		205.00	X 205.00
30	1	K81590-0D150 LAMP ASSY, RR, LH	1.00	205.00		205.00	X 205.00
31	2	SPZ061-0D035 24 BACK SENSOR GREY METALLIC	1.00	149.90		149.90	mm X 149.90
				167.50		167.50	1210.80

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	3980.60 1210.80	12,042.10
	Please acknowledge receipt of vehicle	Parts 4,672.10 Labour 7,290.00 Sublet 80.00 Lubrication/Fluid 0.00 Others 0.00	GST 7.00% 519.40 Less 0.00	842.95	0.00
			Amount Due		12,885.05

Customer Copy