

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBE 7010 A
 TP/AXA

Not Noted
11/10/22
Recovery After Claim

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA

Claim Type: Third Party

Accident Date: 29/05/2022

TP Veh Reg No: PC3222B

Estimate No: ES2291016/YISHUN
 Date: 03 Oct 2022
 Policy No: DMCVSNW00010912201
 Veh Reg No: GBE7010A
 Make/Model: NISSAN CABSTAR 3.0
 Chassis No: JN1SC2F24Z0858110
 Engine No: ZD30008046N
 Reg. Date: 29/02/2016

Estimate Repair Cost to Vehicle No :GBE7010A

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 FRONT RH DOOR	1,590.50	1 PC	1,590.50	✓
2 FRONT RH DOOR OUTER HANDLE	192.60	1 PC	192.60	✓
3 FRONT RH DOOR OUTER GLASS MOULDING	155.90	1 PC	155.90	?
4 FRONT RH DOOR INNER RUBBER	99.50	1 PC	99.50	?
5 FRONT LH DOOR	1,590.50	1 PC	1,590.50	✓
6 FRONT LH CORNAL PANEL	479.90	1 PC	479.90	✓
7 LH HEADLAMP	570.40	1 PC	570.40	?
8 FRONT LH SIDE MIRROR BRACKET	249.20	1 PC	249.20	✓
9 FRONT RH WHEEL ARP PANEL	1,990.10	1 PC	1,990.10	✓
10 FRONT LH SIDE MIRROR STAY OUTER GARNISH	120.00	1 PC	120.00	?
11 FRONT RH WHEEL REAR MUD FLAP	325.00	1 PC	325.00	?
12 RADIATOR SPARE TANK	105.00	1 PC	105.00	✓
			7,468.60	
	Less 10%		746.86	6,721.74
Special Net				
13 COY NAME STICKERS	20.00	2 PCS	40.00	✓
			40.00	40.00
Labour				
14 REMOVE & REFIX FRT LH & RH DOOR ASSY, LOCK ASSY, TRANSFER DOOR ATTACHMENT, FRT LH CORNAL PANEL, SIDE MIRROR, KNOCK & REPAIR FRT RH WHEEL ARP PANEL, FRT LH W/SCREEN PILLAR AND REALIGN THE	1,300.00	1 LA	1,300.00	1000
15 REMOVE & REFIX FRT LH & RH DOOR GLASS	140.00	1 LA	140.00	120
16 PUTTY & RESPRAY ON FRT LH DOOR, CORNAL PANEL, W/SCREEN PILLAR, FRT RH DOOR, WHEEL ARP PANEL	980.00	1 LA	980.00	800
17 RUSTPROOFING	60.00	1 LA	60.00	✓
18 TO REWRITE ADVERTISEMENT	380.00	1 LA	380.00	?
			2,860.00	2,860.00

Total SS 9,621.74

Add GST @ 7% 673.52

Total Amount Payable SS 10,295.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE