



Repair Estimate

VAG Singapore Pte Ltd

48 Toh Guan Road East

#05-136, Enterprise Hub

Singapore 608586

Tel: 6267 9916

Fax: 6267 9313

www.avantage.sg

Date : 29-Sep-2022

Vehicle Num : SME8891L

Make/Model : Mercedes Benz C180 Avantgrade (R17 LED)

Chassis No : WDD2050402R401442

S/N	PARTS	QTY	PRICE	TOTAL
1	RH Front Fender	1	\$ 792.68	\$ bt 792.68
2	RH Front Fender Shield	1	\$ 111.60	\$ m 111.60
3	Front Bumper	1	\$ 1,566.89	\$ de 1,566.89
4	RH Mounting Rail, Front Bumper	1	\$ 18.92	\$ de 18.92
5	RH Sensor, Outer	1	\$ 171.29	\$ cut 171.29
6	Ring Seal, Sensor	1	\$ 9.96	\$ new 9.96
7	RH Headlight	1	\$ 2,700.66	\$ cut 2,700.66
8	RH Front Wheel Rim	1	\$ scr (LR) 904.20	\$ RY 904.20 SN 180
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____				
	TOTAL PARTS		5372	\$ 6,276.20
	Less 10%		10% 4834.80	\$ 627.62
	TOTAL AMOUNT			\$ 5,648.58
	MISCELLANEOUS ITEM		SN 180	
1	Sunderies		\$ 30.00	\$ 22.50 30.00
2	Tuff Kote		\$ 25.00	\$ 25.00
	LABOUR		47.50	
1	Remove and refit RH Front Fender, Shield, Bumper, Mount Rail, Sensor, Headlight and other associate components.		\$ 600.00	\$ 300 600.00
2	Surface preparation, spray paint and polish RH Front Fender, Bumper, Sensor, and other affected areas.		\$ 600.00	\$ 450 600.00
3	Remove, refit & balance RH Front Wheel Rim		\$ 30.00	\$ 30.00
4	Check & adjust Wheel alignment		\$ 100.00	\$ 80 100.00
5	Diagnostic check and erase fault codes after the repair.		\$ 80.00	\$ 80.00
	Tanfilin 97495445 / 62563561		940	
	5/10/22 @ 130pm			
	Tanfilin @ lkkauto.com		4834.80	
	ply Resurvey before paint		180	
	3-4 days		47.50	
			940	
	TOTAL		6602.30	\$ 7,113.58
	GST 7%		44 days	\$ 497.95
	GRAND TOTAL			\$ 7,611.53