



LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

MS First Capital Insurance Ltd
Date : 3 Oct 2022
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLR8119C
CHASSIS NO : JM6BN22A8H0162426
MAKE / MODEL : Mazda 3
DATE OF ACCIDENT: 24 Sep 2022
YOUR INSURED VEHICLE NUMBER : SHB1551P

	<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear bumper / CR	1	\$1,280.00	\$1,280.00 1028/
2	Rear bumper side retainer / BR	1	\$196.00	\$196.00 40/
3	Rear bumper side reflector / ? x nn	1	\$160.00	\$160.00 X
4	Rear LHS taillamp / BR	1	\$840.00	\$840.00 535/
5	LHS rear fender fuel cap / BT	1	\$210.00	\$210.00 158/
6	LHS rear door X R	1	\$1,100.00	\$1,100.00 X
7	LHS rear fender / OD	1	\$780.00	\$780.00 155/
8	LHS rear fender inner liner / CR	1	\$298.00	\$298.00 X
9	LHS rear shock absorber / ? x nn	1	\$598.00	\$598.00 X
10	LHS rear control arm / ? x nn	1	\$372.00	\$372.00 X
11	LHS rear wheel bearing / ? x nn	1	\$238.00	\$238.00 X
LIST TOTAL S\$:				\$6,072.00 2696
20.00% DISCOUNT S\$:				\$1,214.40 -20%
				\$4,857.60 2156.80

	<u>SPECIAL NETT</u>		
1	LHS Rear alloy sports rim / CR	1PC	\$980.00 600/
2	LHS rear door rubber X nn	1PC	\$180.00 X
3	Rear bumper clips / nn	1 SET	\$20.00 /
4	LHS Rear fender inner shield clips / nc	1SET	\$60.00 10/
5	Rear windscreen sealant / nc	1PC	\$80.00 40/
Special Nett Total S\$:			\$1,320.00 670

LABOUR CHARGES

rear bumper side reflector, rear lhs taillamp, rear lhs door, rear lhs fender out to facilitate repairs and replacement & repair LH rocker

1 panel of damaged parts

\$1,500.00 1000

2 To spray Rear LH door, Rear LH fender, Rear bumper

\$1,000.00 800

3 Remove and transfer rear LH door mechanism

\$300.00 X

4 To remove and install rear LH door glass

\$180.00 X

LABOUR TOTAL S\$: \$2,980.00

TOTAL S\$: \$9,157.60

7% GST \$641.03

GRAND TOTAL S\$: \$9,798.63

=4626.80

Steve (LKK)

4/10/21, 11:30am

m R

L/S

My AL y

10 L/S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

MS First Capital Insurance Ltd

Date : 3 Oct 2022

Attn : MOTOR CLAIMS DEPT

SUPPLEMENTARY ESTIMATE

VEHICLE NO : SLR8119C
CHASSIS NO : JM6BN22A8H0162426
MAKE / MODEL : Mazda 3
DATE OF ACCIDENT: 24 Sep 2022
YOUR INSURED VEHICLE NUMBER : SHB1551P

	<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Absorbor rear LH & RH - BT	1 2	\$315.00	\$315.00 157.50 ✓
2	Knuckle rear LH - BT	1	\$403.60	\$403.60 ✓
3	Lower arm rear LH - BT	1	\$454.40	\$454.40 ✓
4	Camber arm rear LH - BT	1	\$142.50	\$142.50 ✓
5	Toe arm rear LH - BT	1	\$67.50	\$67.50 ✓
6	Wheel Brearing rear LH - NRC	1	\$568.80	\$568.80 455 ✓
7	Excle Arm rear LH - BT	1	\$165.00	\$165.00 ✓
8	Disc Rotor rear LH & RH - CUT	1 2	\$615.60	\$615.60 307.80 ✓
LIST TOTAL S\$:				\$2,732.40 2153.30
20.00% DISCOUNT S\$:				\$546.48 -20% 1722.64
				\$2,185.92

LABOUR CHARGES

To labour charge for removing and refixing the above parts out to
1 facilitate replacement of damage parts.

	\$1,500.00 250
LABOUR TOTAL S\$:	\$1,500.00
TOTAL S\$:	\$3,685.92
7% GST	\$258.01
GRAND TOTAL S\$:	\$3,943.93

Steve (LKK)
20/10/22

= 1972.64
main estimate = 4676.80
6599.44
L/S - 5279.55
= 5253.00