

**Wah Hong Motors & Credit Pte Ltd** (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

**TP INSURER: HL Assurance Pte Ltd (HQ)**  
**GANTRY OF LINK @ 819 BUKIT TIMAH ROAD**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	WH1476
Policy No:		Date of Loss:	27/09/2022
Vehicle Reg. No.:	SLB3121L	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	MITSUBISHI OUTLANDER, 2.4 CVT AWD S/R FACELIFT (A)	Vehicle Reg. Date:	01/04/2016
Vehicle Colour:	SILVER		
Engine No:	4B12QS5384	Chassis No:	JMYXTGF3WGZ002559
Odometer:	102725 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	2		
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)		

**COST OF CLAIMS**

	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	1,000.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>1,000.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>70.00</b>
<b>Nett Amount (S\$)</b>	<b>1,070.00</b>

This claim is handled by: THONG ZHONGMING

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 03 Oct 2022)

**Parts:** M1-SUV MITSUBISHI OUTLANDER 2.4 CVT AWD S/R FACELIFT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** Wah Hong Motors & Credit Pte Ltd/SLB3121L/03/10/2022 16:08

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Roof panel (Repair refer to labor)	0.00	0.00	Ry *- F
2	1		*Roof lining garnish RH (Repair refer to labor)	0.00	0.00	Ry *- F
F=Franchise part.						
			Sub Total (S\$)			0.00
			+ Margin on L,N Items 5.00% (S\$)			0.00
			Total Parts (S\$)			0.00

Wah Hong Motors & Credit Pte Ltd/SLB3121L/03/10/2022 16:08. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	100 500.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	200 500.00
Gross Labour Cost (S\$)			1,000.00

Wah Hong Motors & Credit Pte Ltd/SLB3121L/03/10/2022 16:08. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97415749  
wr 5/16/22 e 2pm  
Resurvey after repair  
tanpin@lkkauto.com  
2 days

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: