



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
-			Ref:	CS/LAW22009735/Tqy3e2
NETTO & MAGIN LLC ADVOCATES & SOLICITORS 1 Coleman Street, The Adelphi, #08-05, Singapore 179803			Date:	02/11/2022
			Code:	LAW
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SNC 777K	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From NICHOLAS LEOW	Assign Date	03/10/2022	
2. Vehicle Particulars & Condition				
	Make & Model	LAMBORGHINI AVENTADOR	c.c	6498
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	ZHWEC1ZD9DLA01705	Colour	BLUE
	Odometer	33543 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/30 R20	PIRELLI	6 mm
	L/H Front Tyre	255/30 R20	PIRELLI	6 mm
	R/H Rear Tyre	355/25 R21	PIRELLI	6 mm
	L/H Rear Tyre	355/25 R21	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/08/2022	Inspection Date	03/10/2022
	Survey held at	TOP 93 PTE LTD 51 UBI AVENUE 1, #01-05, PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	