

Celine Fong (LKKAUTO)

From: Nicholas Leow <nicholas@nmlawcorp.com.sg>
Sent: Monday, 3 October 2022 2:16 PM
To: Admin-D (LKKAUTO); 'surveyor'; assignments
Cc: peteree7k@gmail.com
Subject: RE: Request for Pre-Repair Inspection

Dear Yan,

My client has provided the requested quote from the workshop for the repairs as follows:

Lamborghini Aventador LP700
ZHWE1ZD9DLA01705

Front Bumper
\$16000

Bumper Sponge
\$1050

Bumper Bracket x 2

@\$280 each x2 = \$560

Novitec Front spoiler in CF, RH only for LP700 - \$2,750.00

Novitec Front spoiler in CF, LH only for LP700 - \$2,750.00

Novitec Front strut in CF for LP700 - \$3,150.00

bumper centre grille
\$450

Bumper Parking Sensor

@\$220x2 (2 faulty required to replacement) = \$440

Bumper Emblem

\$650

front wheel housing RH:

\$1720

Labour for Installation & Paintwork - \$1500

Total : \$33191.40 (inclusive of gst)

Thank you and please provide us an estimate of the total assessed repair costs by the surveyor so that our client may safely proceed to repair his vehicle after that.

Best regards,

Nicholas Leow

Counsel

NETTO & MAGIN LLC
ADVOCATES & SOLICITORS

Pauline, please adjust the quote accordingly. Thanks.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

→ 3 days to repair

→ 3-4 weeks to wait for parts, need to order.

→ To Resurvey before paint, p/p repair