

TwinCar AUTOMOTIVE PTE LTD

Company Registration and GST No. 200714616M

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 67440510

Fax: 67410510

Email: sales@n51.com.sg

Our Ref:

GBJ 6671 Y

Your ref:

GX 8851 Z

03 October 2022

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : ACTINIUM ENGINEERING PTE LTD

VEHICLE NUMBER : GBJ 6671 Y

YOUR INSURED VEHICLE NUMBER : GX 8851 Z

ACCIDENT ON 23 SEPT 2022 AT ABOUT 10:35 HOURS

ALONG MACPHERSON RD TWDS BENDEMEER RD B4 ALJUNIED RD

We refer to your email / fax dated **03 Oct 2022** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK of Adrian Ling** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Avenue 2

#01-17

Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



Twincar Automotive Pte Ltd

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: