



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No 2 Pandan Crescent  
Singapore 128462, Tel no : 6631 1388



## ESTIMATE

Account Details		Account No.	Customer Details						
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCH1	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233  Mobile: 96889560						
		Document No. 0							
		Document Date 03/10/2022							
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTHB11B1802003118		A25A0237541	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMPCSNW00161062200 ACC DATE:02.10.2022 TOW/DRIVE IN: EXCESS: DATE-IN:03.10.2022 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:							50 80.00
2	B	BP-LAB3 TRANSFER BOOT LID COMPONENT AND MECHANISM TO NEW DOOR SHELL. (NETT)							433.00
3	B	BP-LAB3 REMOVE/REFIX REVERSE CAMERA. (NETT)							216.50
4	B	BP-LAB3 REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR. (NETT)							433.00
5	B	BP-LAB3 CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE.(NETT)							216.50
6	B	BP-LAB3 REMOVE/REFIX REVERSE SENSORS. (NETT)							216.50
7	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL, SPARE WHEEL PAN, R/R AND L/R BODY PANELS, CUT AND WELD PANEL AND FIT NEW PARTS. <i>54 x 866</i>							4330.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total			
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less			
						Amount Due			

Customer Copy



# Borneo Motors



Inchcape  
 Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No.2 Pandan Crescent  
 Singapore 128462, Tel no.: 6631 1368

## ESTIMATE

Account Details		Account No.	Customer Details						
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233  Mobile: 96889560						
		Document No. 0							
		Document Date 03/10/2022							
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTHB11B1802003118		A25A0237541	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
8	B	BP-RES3 SPRAY PAINT ON DAMAGED 742 x 5 AFFECTED PORTION OF CAR.							3710 4081.00
9	Z	BP-SLANT SUPPLY SEALANT (NETT) BOOT AND REAR PANEL							200.00
10	B	BP-MECH3 TO RESET ECU AND REPROGRAMME. (NETT)							216.50
11	1	L64401-33860	PANEL SUB-ASSY, / 80		1.00	902.00		902.00	
12	2	L64510-33271	HINGE ASSY, LUGGAGE		1.00	242.40		242.40	
13	3	L64520-33131	HINGE ASSY, LUGGAGE		1.00	229.10		229.10	
14	4	L64719-33300 C0	COVER, LUGGAGE		1.00	543.90		543.90	
15	5	T90467-08186 C3	CLIP / n/c		14.00	2.70		37.80	
16	6	L64713-33070	COVER, LUGGAGE / n/c		1.00	102.90		102.90	
17	7	L64714-33060	COVER, LUGGAGE / n/c		1.00	102.90		102.90	
18	8	L64650-33040	CLOSER ASSY, LUGGAGE / BT		1.00	1394.60		1394.60	
19	9	L64461-33130	WEATHERSTRIP, / CR4		1.00	272.70		272.70	
20	0	L76801-33721	GARNISH SUB-ASSY, / ?		1.00	604.70		604.70	
21	1	T81204-47010	LAMP SUB-ASSY, / ?		1.00	311.50		311.50	
22	2	L90975-02154	EMBLEM, SYMBOL / n/c		1.00	77.30		77.30	
23	3	L75447-33200	PLATE, LUGGAGE COMPT / n/c		1.00	73.80		73.80	
24	4	L75442-33500	PLATE, LUGGAGE COMPT / n/c		1.00	73.80		73.80	
25	5	L81580-33471	LAMP ASSY, RR, RH / ?		1.00	1149.20		1149.20	
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary			Total		
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others			Less		
							Amount Due		

Customer Copy



# Borneo Motors



Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-850000-9  
No 2 Pandan Crescent  
Singapore 128462. Tel no. : 6631 1388

## ESTIMATE

<b>Account Details</b> China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	<b>Account No.</b> S1000003 / ICCI1	<b>Customer Details</b> Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233 Mobile: 96889560
	<b>Document No.</b> 0	
	<b>Document Date</b> 03/10/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
26	6	L81590-33472 LAMP ASSY, RR, LH	1.00	1149.20		1149.20
27	7	L76817-26040 CLIP, <i>ne</i>	2.00	3.90		7.80
28	8	L52157-33040 SUPPORT, RR BUMPER	1.00	147.30		147.30
29	9	L52158-33040 SUPPORT, RR BUMPER	1.00	147.30		147.30
30	0	L52585-33010 INSERT, RR BUMPER	1.00	27.20		27.20
31	1	L52586-33010 INSERT, RR BUMPER	1.00	27.20		27.20
32	2	L52581-33010 PROTECTOR, RR	1.00	200.30		200.30
33	3	L52582-33010 PROTECTOR, RR	1.00	201.90		201.90
34	4	L52171-33170 REINFORCEMENT, RR	1.00	802.50		802.50
35	5	L52615-33210 ABSORBER, RR BUMPER	1.00	120.90		120.90
36	6	L52155-33020 SUPPORT, RR BUMPER	1.00	85.00		85.00
37	7	L52156-33020 SUPPORT, RR BUMPER	1.00	92.80		92.80
38	8	L52567-33040 RETAINER, RR BUMPER	1.00	149.70		149.70
39	9	L52159-33979 COVER, RR BUMPER	1.00	1403.40		1403.40
40	0	L75895-78030 TAPE, MOULDING, NO.1	2.00	43.00		86.00
41	1	L52105-33020 BUMPER SUB-ASSY, RR	1.00	732.40		732.40
42	2	L891B1-33020 BRACKET, KICK DOOR	1.00	155.20		155.20
43	3	L891B2-06021 SENSOR, KICK DOOR	1.00	749.30		749.30
44	4	S52161-0K040 PIECE, RR BUMPER	17.00	4.50		76.50
45	5	L89348-50130 RETAINER, ULTRASONIC	4.00	19.20		76.80

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature _____ Please acknowledge receipt of vehicle	Charge Summary Parts Labour Sublet Lubrication/Fluid Others	Total  Less  Amount Due
	_____ _____	_____ _____	_____ _____

Customer Copy



Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No.2 Pandan Crescent  
Singapore 128462, Tel no: 6631 1368

## ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC1		Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233  Mobile: 96889560			
			Document No.					
			0					
			Document Date					
			03/10/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHB11B1802003118		A25A0237541	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
46	6	L89348-58130	CLIP, ULTRASONIC	nc ?	4.00	12.90		51.60
47	7	L89341-33220 G0	SENSOR, ULTRASONIC.	nc ?	4.00	491.40		1965.60
48	8	L81910-33040	REFLECTOR ASSY,		1.00	52.80		52.80
49	9	L81920-33030	REFLECTOR ASSY,		1.00	52.80		52.80
50	0	L82182-33240	WIRE, LUGGAGE ROOM,		1.00	192.10		192.10
51	1	L88162-33102	SENSOR, BLIND SPOT		2.00	2163.70		4327.40
52	2	L88163-33040	COVER, BLIND SPOT		1.00	97.40		97.40
53	3	L88173-33040	COVER, BLIND SPOT		1.00	97.40		97.40
54	4	L81550-33592	LAMP ASSY, RR	cm (RH)	1.00	1476.70		1476.70
55	5	L81560-33592	LAMP ASSY, RR	cm (LH)	1.00	1476.70		1476.70
56	6	L81497-33030	COVER, RR	nc	1.00	40.60		40.60
57	7	L81498-33030	COVER, RR	nc	1.00	40.60		40.60
58	8	T81496-60010	GUIDE, RR	nc	2.00	3.90		7.80
59	9	L81496-52020	GUIDE, RR	nc	2.00	2.80		5.60
60	0	L52562-33070	RETAINER, RR BUMPER,	nc	1.00	65.00		65.00
61	1	L52563-33050	RETAINER, RR BUMPER,	nc	1.00	65.00		65.00
62	2	L51931-53050	CARRIER, SPARE WHEEL	nc	1.00	28.10		28.10
63	3	L64779-33290	TRAY, SPARE WHEEL		1.00	280.50		280.50
64	4	L64711-33300 CO	MAT, LUGGAGE		1.00	777.60		777.60
65	5	L64429-33030	BOX, LUGGAGE		1.00	763.60		763.60
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								
			Please acknowledge receipt of vehicle		Parts		Less	
					Labour			
					Sublet			
					Lubrication/Fluid			
					Others		Amount Due	

Customer Copy

Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No 2 Pandan Crescent  
 Singapore 128462, Tel no.: 6631 1388

## ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233 Mobile: 96889560	
		Document No.		
		0		
		Document Date		
		03/10/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
66	6	L58387-33160 C0 PLATE, RR FLOOR	1.00	389.60		389.60
67	7	L58307-33191 PANEL SUB-ASSY, BODY	1.00	908.50		908.50
68	8	L89997-30100 ANTENNA, ELECTRICAL	1.00	78.00		78.00
69	9	L58747-33090 PROTECTOR, QUARTER	1.00	30.90		30.90
70	0	L58748-33100 PROTECTOR, QUARTER	1.00	30.90		30.90
71	1	L67857-33080 PROTECTOR, RR DOOR	1.00	25.30		25.30
72	2	L67858-33080 PROTECTOR, RR DOOR	1.00	25.30		25.30
73	3	L57628-33130 COVER, RR FLOOR SIDE	1.00	420.80		420.80

Steve (LKK)  
 4/10/22, 3:00pm

OO - M 11L  
 13 days  
 EXA - ?  
 P/P  
 by BL Y

KK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No metal mounting money is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature:   
 Date:

Customer's Signature	Charge Summary	Total	36,754.50	
Please acknowledge receipt of vehicle	Parts	26,331.50	GST 7.00%	
	Labour	10,423.00		Less
	Sublet	0.00	0.00	
	Lubrication/Fluid	0.00		
	Others	0.00	Amount Due	39,327.32

Customer Copy