



# Borneo Motors



Inchcape  
 Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No 2 Pandan Crescent  
 Singapore 128462, Tel no. : 6631 1388

## ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233  Mobile: 96889560	
		Document No. 0		
		Document Date 03/10/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMPCSNW00161062200 ACC DATE:02.10.2022 TOW/DRIVE IN: EXCESS: DATE-IN:03.10.2022 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 80.00
2	B	BP-LAB3 TRANSFER BOOT LID COMPONENT AND MECHANISM TO NEW DOOR SHELL. (NETT)				433.00
3	B	BP-LAB3 REMOVE/REFIX REVERSE CAMERA. (NETT)				216.50
4	B	BP-LAB3 REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR. (NETT)				433.00
5	B	BP-LAB3 CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE.(NETT)				216.50
6	B	BP-LAB3 REMOVE/REFIX REVERSE SENSORS. (NETT)				216.50
7	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL, SPARE WHEEL PAN, R/R AND L/R BODY PANELS, CUT AND WELD PANEL AND FIT NEW PARTS. <i>5 x 866</i>				4330.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less  Amount Due

Customer Copy



# Borneo Motors



Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No.2 Pandan Crescent

Singapore 128462, Tel no.: 6631 1388

## ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233  Mobile: 96889560
	Document No. 0	
	Document Date 03/10/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
8	B	BP-RES3 SPRAY PAINT ON DAMAGED 742 x 5 AFFECTED PORTION OF CAR.				3710 4081.00
9	Z	BP-SLANT SUPPLY SEALANT (NETT) BOOT AND REAR PANEL				200.00 ✓
10	B	BP-MECH3 TO RESET ECU AND REPROGRAMME. (NETT)				216.50 ✓
11	1	L64401-33860 PANEL SUB-ASSY, / 80	1.00	902.00		902.00 ✓
12	2	L64510-33271 HINGE ASSY, LUGGAGE	1.00	242.40		242.40 ✓
13	3	L64520-33131 HINGE ASSY, LUGGAGE	1.00	229.10		229.10 ✓
14	4	L64719-33300 C0 COVER, LUGGAGE	1.00	543.90		543.90 ✓
15	5	T90467-08186 C3 CLIP / rrc	14.00	2.70		37.80 ✓
16	6	L64713-33070 COVER, LUGGAGE / rrc (to full trim)	1.00	102.90		102.90 ✓
17	7	L64714-33060 COVER, LUGGAGE / rrc	1.00	102.90		102.90 ✓
18	8	L64650-33040 CLOSER ASSY, LUGGAGE / OT	1.00	1394.60		1394.60 ✓
19	9	L64461-33130 WEATHERSTRIP, / CRV	1.00	272.70		272.70 ✓
20	0	L76801-33721 GARNISH SUB-ASSY, / ?	1.00	604.70		604.70 ✓
21	1	T81204-47010 LAMP SUB-ASSY, / ?	1.00	311.50		311.50 ✓
22	2	L90975-02154 EMBLEM, SYMBOL / rrc	1.00	77.30		77.30 ✓
23	3	L75447-33200 PLATE, LUGGAGE COMPT / rrc	1.00	73.80		73.80 ✓
24	4	L75442-33500 PLATE, LUGGAGE COMPT / rrc	1.00	73.80		73.80 ✓
25	5	L81580-33471 LAMP ASSY, RR, RH / ?	1.00	1149.20		1149.20 ✓

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors



Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No 2 Pandan Crescent  
Singapore 128462, Tel no. : 6631 1388

ESTIMATE

Account Details China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	Account No. S1000003 / ICCI1	Customer Details Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233  Mobile: 96889560
	Document No. 0	
	Document Date 03/10/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
26	6	L81590-33472 LAMP ASSY, RR, LH <i>me</i> X NN	1.00	1149.20		1149.20
27	7	L76817-26040 CLIP, <i>me</i> X NN	2.00	3.90		7.80
28	8	L52157-33040 SUPPORT, RR BUMPER <i>me</i> X NN	1.00	147.30		147.30 ✓
29	9	L52158-33040 SUPPORT, RR BUMPER <i>me</i> X NN	1.00	147.30		147.30 ✓
30	0	L52585-33010 INSERT, RR BUMPER <i>me</i> X NN	1.00	27.20		27.20 ✓
31	1	L52586-33010 INSERT, RR BUMPER <i>me</i> X NN	1.00	27.20		27.20 ✓
32	2	L52581-33010 PROTECTOR, RR <i>me</i> X NN	1.00	200.30		200.30 ✓
33	3	L52582-33010 PROTECTOR, RR <i>me</i> X NN	1.00	201.90		201.90 ✓
34	4	L52171-33170 REINFORCEMENT, RR <i>me</i> X NN	1.00	802.50		802.50 ✓
35	5	L52615-33210 ABSORBER, RR BUMPER <i>me</i> X NN	1.00	120.90		120.90 ✓
36	6	L52155-33020 SUPPORT, RR BUMPER <i>me</i> X NN	1.00	85.00		85.00 ✓
37	7	L52156-33020 SUPPORT, RR BUMPER <i>me</i> X NN	1.00	92.80		92.80 ✓
38	8	L52567-33040 RETAINER, RR BUMPER <i>me</i> X NN	1.00	149.70		149.70 ✓
39	9	L52159-33979 COVER, RR BUMPER <i>me</i> X NN	1.00	1403.40		1403.40 ✓
40	0	L75895-78030 TAPE, MOULDING, NO.1 <i>me</i> X NN	2.00	43.00		86.00 ✓
41	1	L52105-33020 BUMPER SUB-ASSY, RR <i>me</i> X NN	1.00	732.40		732.40 ✓
42	2	L891B1-33020 BRACKET, KICK DOOR <i>me</i> X NN	1.00	155.20		155.20 ✓
43	3	L891B2-06021 SENSOR, KICK DOOR <i>me</i> X NN	1.00	749.30		749.30 ✓
44	4	S52161-0K040 PIECE, RR BUMPER <i>me</i> X NN	17.00	4.50		76.50 ✓
45	5	L89348-50130 RETAINER, ULTRASONIC <i>me</i> X NN	4.00	19.20		76.80 ✓

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less  Amount Due

Customer Copy



Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No.2 Pandan Crescent  
Singapore 128462, Tel no. : 6631 1388

## ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233  Mobile: 96889560			
			Document No.					
			0					
			Document Date					
			03/10/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHB11B1802003118		A25A0237541	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
46	6	L89348-58130	CLIP, ULTRASONIC	nc	4.00	12.90		51.60 ✓
47	7	L89341-33220 GO	SENSOR, ULTRASONIC	nc	4.00	491.40		1965.60
48	8	L81910-33040	REFLECTOR ASSY,	nc	1.00	52.80		52.80
49	9	L81920-33030	REFLECTOR ASSY,	nc	1.00	52.80		52.80
50	0	L82182-33240	WIRE, LUGGAGE ROOM	nc	1.00	192.10		192.10
51	1	L88162-33102	SENSOR, BLIND SPOT	nc	2.00	2163.70		4327.40
52	2	L88163-33040	COVER, BLIND SPOT	nc	1.00	97.40		97.40
53	3	L88173-33040	COVER, BLIND SPOT	nc	1.00	97.40		97.40
54	4	L81550-33592	LAMP ASSY, RR	nc (RH)	1.00	1476.70		1476.70 ✓
55	5	L81560-33592	LAMP ASSY, RR	nc (LH)	1.00	1476.70		1476.70 ✓
56	6	L81497-33030	COVER, RR	nc	1.00	40.60		40.60 ✓
57	7	L81498-33030	COVER, RR	nc	1.00	40.60		40.60 ✓
58	8	T81496-60010	GUIDE, RR	nc	2.00	3.90		7.80 ✓
59	9	L81496-52020	GUIDE, RR	nc	2.00	2.80		5.60 ✓
60	0	L52562-33070	RETAINER, RR BUMPER,	nc	1.00	65.00		65.00 ✓
61	1	L52563-33050	RETAINER, RR BUMPER,	nc	1.00	65.00		65.00 ✓
62	2	L51931-53050	CARRIER, SPARE WHEEL	nc	1.00	28.10		28.10 ✓
63	3	L64779-33290	TRAY, SPARE WHEEL	nc	1.00	280.50		280.50 ✓
64	4	L64711-33300 CO	MAT, LUGGAGE	nc	1.00	777.60		777.60 ✓
65	5	L64429-33030	BOX, LUGGAGE	nc	1.00	763.60		763.60 ✓
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								
			Please acknowledge receipt of vehicle		Parts		Less	
					Labour			
					Sublet			
					Lubrication/Fluid			
					Others		Amount Due	

Customer Copy

Inchoape  
 Co. Reg No. : 196700086Z  
 GST Reg No. : MR-8500000-9  
 No 2 Pandan Crescent  
 Singapore 128462, Tel no.: 6631 1388

## ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICC11	Mr Ong Chu Kiat 233 Bishan Street 22 #04-132 Singapore 570233  Mobile: 96889560
	Document No. 0	
	Document Date 03/10/2022	

Year	Model	Variants	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AXZA10R	AEZGB S1	31/12/2018	SGC8108Y	30134	21647	64UL/SGC8108Y/021022

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB11B1802003118	A25A0237541	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
66	6	L58387-33160 C0 PLATE, RR FLOOR	1.00	389.60		389.60 ✓
67	7	L58307-33191 PANEL SUB-ASSY, BODY	1.00	908.50		908.50 ✓
68	8	L89997-30100 ANTENNA, ELECTRICAL	1.00	78.00		78.00 ✓
69	9	L58747-33090 PROTECTOR, QUARTER	1.00	30.90		30.90 ✓
70	0	L58748-33100 PROTECTOR, QUARTER	1.00	30.90		30.90 ✓
71	1	L67857-33080 PROTECTOR, RR DOOR	1.00	25.30		25.30 ✓
72	2	L67858-33080 PROTECTOR, RR DOOR	1.00	25.30		25.30 ✓
73	3	L57628-33130 COVER, RR FLOOR SIDE	1.00	420.80		420.80 ✓

Steve (LKK)  
 4/10/22, 3:00pm  
 14 + 13 days  
 EXA - ?  
 P/D  
 by RL Y

KK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No metal modification is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature:   
 Date:

Customer's Signature	Charge Summary	Total
Please acknowledge receipt of vehicle Signature: _____ Date: _____	Parts	36,754.50
	Labour	2,572.82
	Sublet	0.00
	Lubrication/Fluid	0.00
	Others	0.00
	<b>Amount Due</b>	<b>39,327.32</b>

36,850.50

Customer Copy