

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : SNM22D207018/C01 Date: 28th Oct 2022

Our Ref : CS/CTI22009777/Gny3m4

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00 Springleaf Tower Singapore 079909 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SNH 2592L ACCIDENT ON 02/10/2022

Instruction was received to inspect the vehicle Reg. No. SNH 2592L. The inspection was conducted on 04/10/2022 at the premises of M/s Car City Auto Centre Pte Ltd, Blk 9006 Tampines Street 93 #01-198, Singapore 528840.

The following vehicle information was recorded:

Registration Number : SNH 2592L

Make/Model : B.M.W. 328I 2.0 AT D/AB 4DR ABS HID NAV

Year of Registration : 2012 Body Colour : White

Chassis Number : WBA3A52070F254125

Engine Capacity : 1997 cc Speedometer Reading : 175806 km

The vehicle sustained damages at the front, n/s front, o/s rear portion and undercarriage. The Estimated repair cost of such vehicle is \$\$37,590.20 (Sin Dollars: Thirty Seven Thousand Five Hundred and Ninety and Cents Twenty Only.) (Include check items \$\$11,899.00Nett) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "uneconomical Total Loss".

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 142,000.00 (est)

Less: LTA Reimbursement Value (RV)

116,177.00) (S\$

Nett Liability S\$ 25,823.00

S\$ 25,823.00

(b) If the vehicle to be "Repair"

Repair Cost (Est) (Include check items S\$11,899.00Nett) S\$ 37,590.20

Nett Liability

S\$ 37,590.20

(a) - (b) =

(S\$ 11,767.20)

The amount of estimated saving of S\$11,767.20 if the vehicle to be written off as "Total Loss" instead of to be repair.

Vehicle Inspected By:

XING GUO QIANG

M.MATAI, AMSAE-A Automotive Assessor

K.K.LAU MSc(Eng M), B Eng(Hons), PEng(UK), MASME(USA), B Bus(Aust), MBA(UK), IEng(UK), MIIE(mech), MinstAEA, MFIEA, MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA), AM CATARI(CAN), M.MATA(USA), M.MdATA(USA), Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.