

Systematic Airconditioning Pte Ltd

29 Senoko Way Singapore 758059

Tel : 64847188 Fax: 64841334

GST No. 199800703G

Contact: Sha (64847188)

Email : shah@systematicaircon.com

Rasul - 4p 90010068

04/10/22 @ 1400

8 days / P/P

Resurvey before paint

Estimation

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

To: AXA Insurance Singapore Pte Ltd

DATE:	28-Sep-22
D.O.A:	22-Sep-22
Your ref:	SHA7746K

Acknowledged by Repairer

Signature:

Date:

OTC ASIA LOGISTIC - YQ2249B

No.	Description	Qty	Unit Price	Amount
1	Supply and replace one (1) length. sliding door track <i>bt</i>	1	\$ 1,200.00	\$ 1,200.00
2	Supply and replace one (1) set. sliding door bearing <i>rec</i>	1	\$ 750.00	\$ 750.00
3	Supply and replace one (1) no. damaged composite panels <i>ca</i>	1	\$ 1,870.00	\$ 1,870.00
4	Supply and replace 2ft Damaged Aluminium chequered plate skirting <i>bt</i>	1	\$ 680.00	\$ 680.00
5	Supply and replace 2ft Damaged Aluminium flatsheet skirting <i>bt</i>	1	\$ 550.00	\$ 550.00
6	1.7 TON ANTEO Tailgate c/w 1600 X 2500mm Aluminium Alloy Platform Inclusive of: - Joystick Control & Foot Control - PE endorsement and load testing - LTA Inspection - Roller Stopper <i>Xm</i>	1	\$ 12,300.00	\$ 12,300.00
7	Supply and replace one (1) no. Rear METAL BUMPER <i>bt</i>	1	\$ 680.00	\$ 680.00
8	Supply and replace one (1) set BRACKET for metal bumper <i>bt</i>	2	\$ 255.00	\$ 510.00
9	Supply and replace one (1) no. rear NUMBER PLATE <i>bt</i>	1	\$ 55.00	\$ 55.00
10	To supply labour and material to PAINT BLACK the rear metal bumper and bracket	300		\$ 550.00
11	To supply labour and material to install rear metal bumper with bracket and rubber stopper (WELDING) To supply labour and material to install box pillars (WELDING)	600		\$ 2,800.00
12	Spray Painting 1K White on (side door & affected area)	400		\$ 800.00
13	Logo Writing on side door (Die Cut)	500		\$ 600.00
14	Supply Labour and Services - Aluminium box -Shift and levelling aluminium box	450		\$ 1,500.00
15	Supply Labour and Services - -To remove, refix and to renew affected parts	300		\$ 2,500.00

Sub Total \$ 27,345.00

7% gst \$ 1,914.15

Bal amount due \$ 29,259.15

Loss of Used 12 days x \$380.00 300

4095

2550

6645

600
300
1200
400
400
4095
650
35
2550