

FORTDELGRO ENGINEERING PTE LTD

PAIR ESTIMATE

VEHICLE NO SHA4777R

MAKE : TOYOTA

MODEL : PRIUS

DOA 01.10.22

INS. INCOME

MVA JUMANI

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
FRT BUMPER	1		\$ 586.18
HEADLAMP ASSY LH	1		\$ 2,637.60
FOG LAMP RH/LH	1		\$ 920.00
FRT BUMPER CLIPS	10		\$ 22.00
FRT BUMPER TOW COVER RH/LH	1	28.38	\$ 56.76
FRT RADIATOR GRILLE	1		\$ 438.00
FRT BUMPER GRILLE	1		\$ 193.18
FRT BUMPER SONGE			\$ 78.80
EMBLEM 'H'			\$ 88.00
HEADLAMP CENTRE PANEL			\$ 364.98
FRT BUMPER BEAM			\$ 812.89
FRT RH BUMPER SIDE BRACKET LH			\$ 82.30
HEADLAMP PANEL LH		240.1	\$ 480.20
FRT NUMBER PLATE GARNISH			\$ 99.00
		4681.52	
		3511.14	
SUB TOTAL			\$ 6,859.86
LESS 25%			\$ 1,714.96
DISCOUNTED TOTAL			\$ 5,144.90
FRT NUMBER PLAET		NET 50	\$ mis 50.00
		10% - 45	
			\$ 50.00
LABOUR CHARGE			
PANEL BEAT			\$ 350 800.00
SPRAYPAINT			\$ 250 300.00
CHECK WIRING			\$ 30 50.00
TUFF KOTE			\$ X m 50.00
TOWING FEE			\$ X m 60.00
REMOVE/REFIX A/C AND REFILL GAS			\$ X m 120.00
		630	
TOTAL LABOUR		4186.14	\$ 1,380.00
ESTIMATE TOTAL		453350	\$ 6,574.90
		2 days	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjun 97475749
up 3/10/22 @ 4pm
LBS Rising after repair
Tanjun Clikanto. n
2 days