



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CHAN KIAN CHUAN			Ref: CS3/ASM22000933/Vty3e2-1 Date: 12/10/2022 Code: AXA2	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SHD 4233C	Veh. Inspected	FBK 2803E	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S2M03RYP	Excess (\$)	0.00	
Assign From	CHAN KIAN CHUAN	Assign Date	26/01/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CB400SF	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	NC421603264	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	120/60-70	TIMSUN	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	120/60-70	TIMSUN	6 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	18/01/2022	Inspection Date	27/01/2022	
Survey held at	MOTOPLEX PTE LTD 10 KAKI BUKIT ROAD 2 #01-24 FIRST EAST CENTRE SINGAPORE 417868			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	