



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS/GAI22009829/Kny3m4 Date: 21/06/2023  Code: GAI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLL 4237C	Veh. Inspected	SLL 3722A
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000001250	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	05/10/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	SUBARU LEGACY (A)	c.c	2457
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JF1BP9KV58G071266	Colour	BLACK
Odometer	327821 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/40R18	YOKOHAMA	4 mm
L/H Front Tyre	235/40R18	YOKOHAMA	4 mm
R/H Rear Tyre	235/40R18	YOKOHAMA	5 mm
L/H Rear Tyre	235/40R18	YOKOHAMA	5 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	03/10/2022	Inspection Date	13/10/2022
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	