来發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267 GST No: M2-0128609-3 UEN: 199407592C

ESTIMATE

EST. No: EST0030453 Quek Jwee Hua Benedict

Page1 Your ref. TP-SLL 4237C GAI 73066 Payment

Attn

Vehicle No ...: SLL 3722A

Vehicle Model: Subaru Legacy Wagon

Accident on ..: 3/10/2022

Not Nothern 11 Sup & 5600/ \$5800 Benny Afre Paint Fday

		1 04	ag,			
Quantity Unit	Description	Unit price Disc. pct.	Amount			
	Supply of Parts - Nett item:					
1.00 Pc 1.00 Pc 1.00 Pc 1.00 Pc 1.00 Pc 4.00 Pcs 4.00 Pcs 1.00 Pc 4.00 Pcs 1.00 Pc 1.00 Pc 1.00 Pc	Bonnet 99/ Headlamp LH Headlamp RH Front radiator grille 'B' specs Front radiator grille logo emblem Front radiator grille clips (big) Front radiator grille clips Front bumper Front bumper clips Rear tailgate /69/ Rear bumper Rear windscreen c/w mouldings 7 Special nett item:	102.60 4.00 4.00 660.00 4.00 1,648.00	Mr. 991.00 X Sn. 2,161.00 X 2,161.00 X 04 632.20 X Mr. 16.00 X Mr			
1.00	Solar film + installation Reversing sensor with installation (4 pcs)	350.00 280.00	na 350.00 A na 280.00 Zean			

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种款式的单身及给甲炔键号企业的 除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair benefit, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發(明記)摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267 GST No: M2-0128609-3 UEN: 199407592C

ESTIMATE

EST. No: EST0030453 Quek Jwee Hua Benedict

Your ref. TP-SLL 4237C GAI Payment

Attn

Vehicle No ...: SLL 3722A Vehicle Model : Subaru Legacy Wagon

Accident on ..: 3/10/2022

Quantity Unit	Description	Unit price	Disc. pct.		Amount	
1.00	Front number plate	70.00		con	70.00	45/n
	Labour & Misc:					
1.00	To dismantle + refix rear windscreen	160.00			160.00	1201
1.00	To supply sealant	40.00			40.00	~
1.00	To dismantle + refix rear tailgate spoiler + reversing camera, etc	150.00			150.00	12cl
1.00	To straighen front body, to knock dents on front support panel, front fender LH & RH and renew of parts	550.00			550.00	
1.00	To straighten rear body, to dismantle + renew parts	500.00			500.00	001
1.00	To spray paint (front portion)	800.00			800.00	-61

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。 除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267 GST No: M2-0128609-3 UEN: 199407592C

ESTIMATE

EST. No: EST0030453 Quek Jwee Hua Benedict

Our ref 22.10.03

Payment

Date 4/10/2022

Attn:

Vehicle No ...: SLL 3722A

Vehicle Model: Subaru Legacy Wagon

Accident on ..: 3/10/2022

Description	Unit price	Disc not	A 122 C 1 1 1 1
To spray paint (rear portion)	600.00	D130. pot.	Amount 600.00 400
		To spray paint (roos portion)	To spray paint /roor portion)

Sub-Total GST 7.00% Total

13,914.80 974.04

14.888.84

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。 除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."